COUNTY SURVEYOR'S RECORD, DOUGLAS COUNTY, OREGON

223.

BUSHONG & CO. PORTLAND, ORE. 87545

Survey No. 3-20 *Made on* Nov. 18-28 1925	*Survey No.* *Made on*
In Town. 26 *Range* 4 *Sec.* 23-24-26	*In Town.* *Range* *Sec.*
Made for Frank Burkett	*Made for*
Purpose of Establishment of lines	*Purpose of*
Surveyor W.H.Wood Chain Crear, King Axe Casebeer	V3 E'' FN"LL" - MAR IN C.S. FILE No 3/20

At South ~~east~~ WEST corner D.L.C. No. 43, I find old stake rotted out, and at B.T. which is a B. Oak S 85°W 13 lks. I renew this corner by settin g an Iron Pipe 1/2 x 2 x 2 feet. thence

N 0°30'W 47.90 ch. Fall 2.32 west of N.W. Corner of Burketts as set by Eppstein

Return to S.W. Cor and run

N 2°21'E On West line of D.L.C. No. 43

3.70 Set iron Pipe ("C) on map
8.70 Set iron pipe ("D) on map
47.90 Northwest corner of Burketts land, as set by Eppstein

Re-established corner to sections 23-24-25-26 , I find an old B.T. S 41°W 4.73, also rotted stake for corner set by a previous surveyor, I renew this corner by setting an iron pipe 5/8 by 2 feet, from which

18"Pine N 8°W 1.82 ~~lks~~ CH.)
15"Pine S 59½E 82 lks) Trees marked by Cain

F.B. 33 Pg. 2

Mark 18"Pine N 22°E 2.25 B.T. S 24 C.S.

North 20.00 chains set temporary point
~~40~~00 chains set temporary point, and find no trace of corner orm B.TS
80.87 chains, fall 53 lks East of Section Corner 23-24-13-14

I return to corner of 23-24-25-26 and run

N 0°22'W 20.22 set iron pipe for 1/16 corner
~~40~~043 set 1/4 corner by proportional measurment by setting a fir stake 3 x 3 x ~~2~~ scribed 1/4 S and marked

A Fir 12" in dia. N 26°W 26 lks. 1/4 S 23 C.S.
Laurel 15 in dia. N 80½ E 20 lks. 1/4 S 24 C.S.

80.87 to section corner 23-24-13-14

From corner to 23-24-25-26, I run

West 20.00 and set a temporary point
40.11 intersect 98 lks South of 1/4 corner which I re-established

I find old B.T. Fir 30" N 79°E 1.10 , I set an iron pipe for corner and mark a Fir 8" in dia. S 25°W 77 lks scribed 1/4 S 26 B.T. C.S.

From corner to 23-24-25-26- I run

N 88°40'W On true line between Sec. 23-~~24~~ 24

20.05½ Set iron pipe for 1/16 corner

40.00 1/4 corner between 23/26

From corner to 23-24-25-26 I run

South 42.79 find stumps of B.T.s 54 lks. East
82.81 Find 2 B.T.s O.K. 108 lks East

From Corner to Sections 23-24-25-26 I run

S 0°40'E On true line between sections 26 and 25

42.79 Re-establish 1/4 corner from Fir stump 48" bears N 87°E 25 lks. and a Fir stump 40" bears N 75°W 95 lks. Set a oak stake 4 x 4 x 3 and scribed 1/4 S and mark 6"Fir N 75°W 41 lks scribed 1/4 S B.T. C.S. 12" Fir S 25°E marked by some previous surveyor

82.81 Re-establish corner to Sections 25-26-35-36, and set an oak stake 4 x 4 x 3 marked S 25 26 35 36 from which
Old B.T. Laurel 24" bears N 25°W 21 lks.
Old B.T. B. Oak 18" bears N 87°E 68 lks.
Mark Fir 15" bears S 48°E 23 lks. B.T. S 56 C.S.
Mark Fir 12" S 31 W 62 lks. B.T. S 35 C.S.