

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 1 Page(s) 407-08)

Fir 6" dia., which I mark for cor. to secs. 18 & 19, T19S R8W S18 on NE., T19S R8W S19 on SE. faces, with 3 notches on N. & S. edges; from which
 A Cedar 20" dia., bears N.30°E., 32 lks. dist. mkd. T19S R8W S18 BT.
 A Cedar 24" dia., bears S.70°E., 29 lks. dist. mkd. T19S R8W S19 BT.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13022)

The cor. of secs. 18 & 19 only, determined at record distance from each of the original bearing trees:
 A Cedar 29" dia., bears N.60°E., 32 lks. dist. with a healed blaze facing the corner. (Rec. brg. N.30°E.)
 A Cedar 26" dia., bears S.53½°E., 29 lks. dist., with scribe marks T19S R8W S19 BT visible on unhealed blaze facing the corner. (Rec. brg. S.70°E.)
Find no trace of original 6" dia. Fir corner tree.
At the corner point
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:
 T 19 S T 19 S
 S 24 S 18
 S 19
 R 9 W R 8 W
 1957

Fd. OK, March 1982 by L. Roberts - M 91-73

BLM Resurvey by John P. Farnsworth, Cadastral Surveyor, under Group #1076, surveyed Sept. 1981/April 1983 - (DCSO records Vol. 45 Page(s) 17469-70)

The cor. of secs. 18 & 19, monumented with an iron post, 2" dia., firmly set, projecting 14" above ground, with brass cap mkd. in 1957, from which the remains of the orig brg trees:
 A Cedar 29" dia., bears N.60°E., 32 lks. dist., with healed blaze.
 A Cedar snag, size indeterminate, S.53½°E., 29 lks. dist., with scribe marks S R8W S19 BT visible on opened blaze.
and a new bearing tree:
 A Cedar 48" dia., bears S.29°E., 27 lks. dist. mkd. T19S R8W S19 BT.