

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION W 1/4 cor for Sec 7 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 1 Page(s) 409)

Set post 4 ft. long, 4" sq., 24" in the ground mkd. ¼ S on W. face; from which

A Fir 30" dia., bears S.33°E., 24 lks. dist. mkd. ¼ S BT.

A Fir 15" dia., bears N.40°W., 60 lks. dist. mkd. ¼ S BT.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13026)

The ¼ sec. cor. of sec. 7 only, determined at record bearing and distance from each of the original bearing trees:

A Fir 53" dia., bears N.40°W., 60 lks. dist. plainly blazed and healed.

A Fir 27" dia., bears S.33°E., 24 lks. dist. plainly blazed and healed.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T 19 S

¼ S 7

R 8 W

1957

from which a new bearing tree:

A Hemlock 12" dia., bears N.1½°E., 44 lks. dist. mkd. ¼ S7 BT.

Fd. BC & 4 BTs, 5/2009 by Corey Woodruff, M159-30

Jerry Estabrook - For: Roseburg Resources - 8/2020 - M179-69

Found - A 2" iron pipe with 3½" brass cap marked "T19S R8W ¼ S7 1957" per BLM plat #1245 and DCSO records Vol. 31 Pg 13026. Set steel post along side.

A rotten 28" fir stump with healed face and tag bears S.33°E., 16.8'. GL0 record 15.84'.

A rotten 54" fir stump with no visible marks and tag bears N.39°W., 39.7'. GL0 record N.40°W., 39.6'.

A 17" Fir with healed face and tag bears N.22°38'E., 31.2'.

A 15" fir with healed face and tag bears S.52°11'W., 61.23'.

New BT - A 16" Fir, face scribed "X BT" with X-chop and tag bears S.7°W., 7.0' to a spike at side center.

GARMIN ETREX HAND HELD GPS (not survey grade)

N: 43°55'47.3" W: 123°42'13.8"