

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; & 4 & 5, T20-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 2 Page(s) 461)

Set post 6" dia., 4 ft. long, with marked stone 12" in ground for cor. to secs. 32, 33, 4 & 5, marked T19S S33 on NE.; R8W S4 on SE.; T20S S5 on SW.; S32 on NW. faces, with 2 notches on W. & 4 on E. edges; from which
Fir 20" dia., bears N.20°E., 51 lks. dist. mkd. T19S R8W S33 BT.
Maple 10" dia., bears S.44°E., 8 lks. dist. mkd. T20S R8W S4 BT.
Fir 20" dia., bears S.50°W., 27 lks. dist. mkd. T20S R8W S5 BT.
Fir 30" dia., bears N.45°W., 12 lks. dist. mkd. T19S R8W S32 BT.

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 504)

Failed to find the corners on the N. bdy. of T20S R8W, except those on the N. bdy. of sec. 1. After diligent search I fail to find any other of the original marks of this line or any marks of lines coming in from the South. (This excerpt was taken from Vol. 2 Pg. 501)

Set post 4 ft. long, 4" sq., 24" in ground for cor. to secs. 4, 5, 32 and 33 marked T19S S33 on NE.; R8W S4 on SE.; T20S S5 on SW.; and S32 on NW. faces, with 4 notches on E. & 2 notches on W. edges; from which
A Fir 24" dia., bears N.51°E., 43 lks. dist. mkd. T19S R8W S33 BT.
A Fir 24" dia., bears S.16½°E., 29 lks. dist. mkd. T20S R8W S4 BT.
A Fir 36" dia., bears S.51°W., 27 lks. dist. mkd. T20S R8W S5 BT.
A Fir 18" dia., bears N.16½°W., 47 lks. dist. mkd. T19S R8W S32 BT.

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298 - Surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12918)

Point for the sec. cor. as determined from the original bearing trees:
A Fir 31" dia., bears N.51°E., 43 lks. with healed blaze facing SW.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; & 4 & 5, T20-8

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

A Fir 31" dia., bears S.16½°E., 29 lks., with healed blaze facing NW.

A stump hole of a Fir bears S.51°W., 27 lks..

A Fir 25" dia., bears N.16½°W., 47 lks. with healed blaze facing SE.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

T19S	R8W
S 32	S 33
S 5	S 4
T20S	
1952	

from which

A Fir 24" dia. bears S.6°45'W., 51 lks mkd. T20S R8W S5 BT

A Fir 30" dia. bears N.29°45'W. 48 lks mkd T19S R8W S32 BT

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2670, Surveyed May 2012/June 2013 - (DCSO records Vol. 58 Pages 23046-7)

 The cor. of secs. 4, 5, 32, & 33, on the N. bdy. of the Tp., monumented with an iron post, 2" dia., firmly set, projecting 12 ins. above ground, with a brass cap (properly) mkd.

from which the remains of original bearing trees

A fir stump, 36" dia., bears N.51°E., 28.4 ft., with a healed blaze.

A decayed fir stump, 25" dia., bears S.16½°E., 19.1 ft., no marks visible.

A fir stump, size indeterminate, bears N.16½°W., 26.8 ft., with a healed blaze. (Record, 31.0 ft.)

and the remains of the BTs mkd. by Lytle and Norseth in 1952

A fir snag, 29" dia., bears S.6¾°W., 33.7 ft., with a healed blaze.

A decayed fir stump, size indeterminate, bears N.29¾°W., 31.7 ft., with a healed blaze.

and new bearing trees

A fir, 15" dia., bears N.55¾°E., 16.3 ft., mkd. T19S R8W S33.

A hemlock, 37" dia., bears S.9¾°E., 38.7 ft., mkd. T20S R8W S4 BT.

A fir, 11" dia., bears S.67¼°W., 16.6 ft., mkd. T20S R8W S5 BT.

A fir, 12" dia., bears N.41°W., 21.9 ft., mkd. T19S R8W S32 BT.

NAD 1983 (2011)

Latitude: 43°51'46.26"N. Longitude: 123°39'32.65"W.

continued next page

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; & 4 & 5, T20-8

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ron Rice, NW Land Surveying - April 2013 - C.S. File 65/78-31

Condition Report

Found - 1952 GLO brass cap with the following accessories:
34" D.Fir stump bears N.51°E., 28.4 ft - healed face
24" D.Fir stump bears S.16½°E. 19.1 ft - healed face
24" D.Fir rotted stump bears N.16½°W., 31.0 ft. - no marks
28" D.Fir snag bears S.6¾°W., 33.7 ft. - healed face
D.Fir stump indeterminate diameter bears N.29¾°W., 31.7 ft. - no marks
36" Hem. bears S.9¾°E., 38.7 ft. - scribing visible (2012 BLM)
12" D.Fir bears S.67¼°W., 16.6 ft. - scribing visible (2012 BLM)
12" D.Fir bears N.41°W., 21.9 ft. - scribing visible (2012 BLM)
15" D.Fir bears N.55¾°E., 16.3 ft - scribing visible (2012 BLM)
Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East

Fd. ok by R. Rice, 10/2014 - M168-56