

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 524)</p> <p>-----</p> <p>Set post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., mkd: 1/4 S on W face; from which</p> <p> A Fir, 48" dia., bears West 15 lks., mkd: 1/4 S BT</p> <p> A Fir, 12" dia., bears East 55 lks., mkd: 1/4 S BT</p>
<p>BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12933)</p> <p>-----</p> <p>Point for the 1/4 sec. cor. of secs. 32 & 33, as determined from the remains of the orig. BTs:</p> <p> A Fir, 55" dia., bears West 15 lks., showing old blaze facing E.</p> <p> A Fir stump bears East 55 lks., showing old axe scars.</p> <p>At the corner point</p> <p>Set an iron post, 3' long, 1" dia., 28" in the ground, with brass cap mkd:</p> <p style="text-align: center;"> 1/4 S 32 S 33 1952</p> <p>from which</p> <p> A Fir, 30" dia., bears N.83°E., 56 lks., 1/4 S33 BT.</p>
<p>Ron Rice - for: Oxbow Timber 1 LLC - Oct. 2014 - M168-56</p> <p>-----</p> <p>Found - 1952 GLO brass cap with the following accessories:</p> <p> 55" D.Fir snag bears west 9.9' - healed face</p> <p> Record fir stump bearing East not positively identified</p> <p> 30" D.Fir stump bears N.83°E., 38.9' - scribing visible</p> <p>New BTs-</p> <p> 16" D.Fir bears N.26°W., 10.3' - Blazed, scribed 1/4 S32 BT.</p> <p> 21" D.Fir bears S.54°W., 15.9' - Blazed, scribed 1/4 S32 BT</p> <p> 17" D.Fir bears S.67°E., 46.8' - Blazed, scribed 1/4 S33 BT</p> <p> 22" Hemlock bears N.66°E., 27.3' - Blazed, scribed 1/4 S33 BT</p> <p> Steel post adjacent to corner</p>
<p>Fd. BC & 6 BTs by R. Rice Oct. 2015 - M170-25</p>
<p style="text-align: right;">1</p>