

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 524-5)

Set post, 4 ft. long, 4" sq., 24" in ground, for cor. to secs. 28, 29, 32, & 33, marked T19S S28 on NE, R8W S33 on SE, S32 on SW, S29 on NW faces, with 4 notches on E and 1 notch on S edges; from which

- A Fir, 8" dia., bears N.41°E., 28 lks., mkd: T19S R8W S28 BT.
- A Fir, 18" dia., bears S.65½°E., 19 lks., mkd: T19S R8W S33 BT.
- A Fir, 24" dia., bears S.48°W., 35 lks., mkd: T19S R8W S32 BT.
- A Fir, 30" dia., bears N.73°W., 19 lks., mkd: T19S R8W S29 BT.

BLM Resurvey by Marvin J. Lytle & Palmer Norseth, under Group #298, surveyed May/Aug 1952 - (DCSO recs Vol 31 Pgs 12933-34)

The cor. of secs. 28, 29, 32, & 33 as determined from the remains of the orig. BTs:

- A Fir, 42" dia., bears S.51°E., 19 lks., mkd. with a healed scar facing NW. (Rec. bearing, S.65½°E.)
- A Fir, 35" dia., bears S.45°45'W., 35 lks., showing old scar facing NE (Rec. bearing S.48°W.)
- A Fir, 47" dia., bears N.84¼°W., 19 lks., old blaze facing E. (Rec. bearing, N.73°W.)

At the corner point

Set an iron post, 3' long, 2" dia., 20" in the ground to solid rock and in a mound of stone to top, with brass cap mkd:

T19S	R8W
S 29	S28
S 32	S 33
1952	

from which

- A Fir, 50" dia., bears N.20°45'E., 77 lks., mkd: T19S R8W S28 BT.
- A Fir, 17" dia., bears S.14°W., 52 lks., mkd: T19S R8W S32 BT.

Douglas Co. Surveyors Office - Gary E. Commons - Pete Earle - 2/25/1975 - C.S. File 57/17-20

Found - 1952 US GLO brass cap on I rod surrounded by mound of rocks.

An orig. 18" Fir, S.51°E., 12.5 ft., (rec. S.65½°E.) is now 42" stump capped. (Cont. next page)

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An orig. 24" Fir S.45°45'W., 23.1 ft., (rec. S.48°W.) is now 35" stump capped.  
An orig. 30" Fir N.84°15'W., 12.5 ft., (rec. N.73°W) in now 47" stump capped.  
The bearings on these BTs agree with those of 1952 dependant resurvey.  
Also found -  
    A 17" Fir, S.14°W., 34.3 ft. Is now a capped stump. Scribing visible on top and bottom of scar but center is burned.  
    A 50" Fir, N.20°45'E., 50.8 ft., is now a hollow burnt stump tipped and sliding down hill.  
This corner lies approx. 400 ft. south of log landing on steep west slope. We do not remonument.

Fd. Ok by W. Eimstad, 4/1980 M 84-77

Ronald L Rice - For: Oxbow Timber 1 LLC - Oct. 2015 - M170-25  
-----  
Found - GLO Brass cap dated 1952, with the following accessories:  
38" metal capped fir stump bears S.51°E., 12.5' - no marks.  
35" fir stump record metal cap missing bears S.45¼°W., 23.1' - no marks.  
17" metal capped fir stump bears S.14°W., 34.3' - rotted face.  
New BTs- 20" D.Fir bears N.89°E., 7.5' - blazed, scribed T29S R8W S28 BT  
12" D.Fir bears N.60°W., 5.6' - blazed, scribed T29S R8W S29 BT  
Steel post adjacent to corner.

Fd. as per rec. 12/2016, Ron Rice, M172-67