

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Cor. Secs 4, 5, 8 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 532)

Set post, 4 ft. long, 4 ins sq., 24 ins. in ground, for cor. to secs. 8, 9, 4, & 5, marked T19S S4 on NE, R8W S9 on SE, S8 on SW, S5 on NW faces, with 5 notches on S and 4 notches on E edges; from which
A Fir, 6 ins. dia., bears N.31 3/4°E., 68 lks., mkd: T19S R8W S4 BT.
A Fir, 24 ins. dia., bears S.44 3/4°E., 141 lks., mkd: T19S R8W S9 BT.
A Fir, 36 ins. dia., bears S.69°W., 82 lks., mkd: T19S R8W S8 BT.
A Fir, 18 ins. dia., bears N.21 3/4°W., 116 lks., mkd: T19S R8W S5 BT.

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12944)

Point for the cor. of secs. 4, 5, 8, & 9, determined from the remains of the orig. BTs:
A Fir, 45 ins. dia., bears S.44°45'E., 41 lks., scribed R8 on nearly healed old blaze.
A Fir stump, badly decayed, bears S.69°W., 79 lks., (Rec. is 82 lks.)
A Fir stump, bears North, 112 lks., evidently the stump on the line tree noted in the record. lks., mkd: 1/4 S BT
At corner point
Set an iron post, 3 ft. long, 2 ins. dia., 27 ins. in the ground, with brass cap marked:
T19S R8W
S 5 | S 4
S 8 | S 9
1952
from which
A Fir, 38 ins. dia., bears N.83 1/4°E., 62 lks., mkd: T19S R8W S4 BT.
A Fir, 26 ins. dia., bears S.40°45'E., 75 lks., mkd: T19S R8W S9 BT.
A Fir, 7 ins. dia., bears S.64 1/2°W., 21 lks., mkd: T19S R8W S8 BT.
A Fir, 30 ins. dia., bears N.47 1/2°W., 84 lks., mkd: T19S R8W S5 BT.

continued next page

1

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Lane Co Surveyors Office - Bruce Bothel & Stuart Duce -
2/11/2015 (added 5/27/2021) - C.S. 65/109-14 (Lane Index 16004)

-
- Found - A 2½" Brass cap (property mkd) atop a 2" I. post,
16" above ground, leaning southerly returned it
to vertical and built a large stone mound.
A 30" peeled tin capped Fir stump bears S.44°45'E.,
@ 26.9' to CTR (S.44¾°E., @ 27.1') 1891.
A 36" peeled tin capped Fir stump bears N.83°47'E.,
@ 39.9' to CTR (N.83¾°E., @ 40.9') 1952.
A 40" tin capped Fir stump with healed face bears
S.40°46'E. 49.4' to CTR (S.40°45'E. 49.5') 1952
A 36" tin capped Fir stump with marks bears
N.47°08'W., 55.5' to CTR (N.47½°W., 55.4') 1952
16" D.Fir w/healed face S.61°50'W., @ 13.7' to CTR
New - 15" D.Fir marked "CSBT" N.41°35'E., @ 19.0' to CTR
6" D.Fir marked "CSBT" S.39°47'E., @ 11.9' to CTR
12" D.Fir marked "CSBT" N.49°41'W., @ 15.2' to CTR
Note - BTs: Distance shown is to an aluminum nail set at
side/center of live trees.

Geographic map location: - not of survey grade accuracy
NAD 83/91 VALUES: Lat: N 43°56'11.1" Long: W 123°39'31.9"

Robert A. Cook - For: Roseburg Forest Products - 4/2021 -
M179-34

Condition report

- Found - 1952 GLO brass cap up 4" in a mound of stone and "T"
post 0.8' North.
45" D.Fir stump with tin lid S.44°E. 26.6 ft.
(S.44°45'E., 41 lks. per 1891 GLO)
30" D.Fir stump with tin lid S.41°E., 49.4 ft.
(S.40°45'E., 75 lks. per 1952 BLM)
29" D.Fir stump with tin lid N.48°W., 55.2 ft.
(N.47°30'W., 84 lks. per 1952 BLM)
7" D.Fir (S.39°47'E., 11.9 ft. per Lane Index 16004)
healed face.
16" D.Fir (S.61°50'W., 13.7 ft. per Lane Index
16004) healed face.

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.
