

PRIMARY CORNER DESCRIPTION Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 531)

Set post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on N face; from which

 A Fir, 6" dia., bears S.31 3/4°E., 74 lks., mkd: ¼ S BT

 A Fir, 8" dia., bears N.5 3/4°W., 84 lks., mkd: ¼ S BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12942)

Point for the ¼ sec. cor. of secs. 9 & 16 as determined from the orig. BTs:

 A Fir, 30" dia., showing healed blaze facing S., bears N.5°45'W., 84 lks.

 A Fir stump showing a partly decayed blaze, bears S.31°45'E., 74 lks.

At the corner point

Set an iron post, 3' long, 1" dia., 28" in the ground, with brass cap marked:

¼ $\frac{S\ 9}{S\ 16}$

 1952

from which

 A Fir, 15" dia., bears N.68°45'E., 31 lks., mkd: ¼ S9 BT.

 A Fir, 10" dia., bears S.46°W., 28 lks., mkd: ¼ S16 BT.

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.