

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor. Secs 9, 10, 15, & 16

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 523)

-----

Fir, 20" dia., which I mark for cor. to secs. 15, 16, 9, & 10, T19S S10 on NE, R8W S15 on SE, S16 on SW, S9 on NW faces, with 4 notches on S & 3 notches on E edges; from which

- A Fir, 12" dia., bears N.74½°E., 25 lks., mkd: T19S R8W S10 BT.
- A Fir, 18" dia., bears S.51¼°E., 50 lks., mkd: T19S R8W S15 BT.
- A Fir, 8" dia., bears S.56½°W., 40 lks., mkd: T19S R8W S16 BT.
- A Fir, 18" dia., bears N.20°W. 21 lks. mkd: T19S R8W S9 BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12930)

-----

(At N.0°47'E., 40.26 chains from the 1/4 Cor. of secs. 15 & 16) The cor. of secs. 9, 10, 15, & 16, which is marked with a dead fir, 22" dia., with partially healed blazes in each quadrant, all showing scribe marks, from which the orig. BTs:

- A Fir, 26" dia., bears N.74½°E., 25 lks., with old blaze on SW face.
- A stump hole of a fallen Fir, 36" dia., bears S.51½°E., 50 lks.
- A Fir stump, 10" dia., bears S.56½°W., 40 lks., with a resin scar facing the corner.
- A stump hole of a fallen Fir, 36" dia., bears N.20°W., 21 lks.

(At N.0°47'E., 40.21 chs from the 1/4 Cor. of secs. 15 & 16) Point for the witness to the cor. of secs. 9, 10, 15, & 16. Set an iron post, 3' long, 1" dia., 27" in the ground, with brass cap mkd:

W	C
T19S	R8W
S 9	S 10
S16	S 15
1952	

See 2018 BLM resurvey, Position of the WC is now an AP. Orig. corner tree removed, BC set.

from which

- A Fir, 26" dia., bears N.73½°E., 28 lks., mkd: WC T19S R8W S10 BT.
- A Fir, 34" dia., bears S.66°45'E., 67 lks., mkd: WCT19S R8W S16 BT.
- A Fir, 28" dia., bears S.28°W., 41 lks., mkd: WC T19S R8W S16 BT.
- A Fir, 36" dia., bears N.72°W., 37 lks., mkd: WC T19S R8W S9 BT.

cont.

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ronald Rice - For: Oxbow Timber 1 LLC - Feb. 2015 - C.S. 65/88-3

-----  
Found - 1952 GLO brass cap witness corner with the following accessories:  
Rotted D.Fir stub bears N.73½°E., 18.5' - no marks  
Record 34" Fir bearing S.66¾°E., - Down  
31" D.Fir snag bears S.28°W., 27.1' - healed face  
36"x11' Rotted D.Fir stub bears N.72°W. 24.4' - no marks.  
At the true corner position N.0°47'E., 3.3' of the 1954 GLO witness corner found a 22"x8' D.Fir stub - no marks with the following accessories:  
26" Rotted D.Fir stub bears N.74½°E., 16.5' - no marks  
Record 10" Fir stump S.56½°W. - not found  
New BTS this survey referenced to true corner position  
16" D.Fir bears N.3°W 11.8' - blazed, scribed T19S R8W S9 BT.  
21" D.Fir bears N.84°E., 31.7' - blazed, scribed T19S R8W S10 BT  
13" D.Fir bears S.23°E., 6.4' - blazed, scribed T19S R8W S15 BT  
Steel post adjacent to corner

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2846, surveyed June 2016 - Nov. 2016 - (DCSO records Vol. 59 Page(s) 23816-7)

-----  
The witness cor. to the cor. of secs. 9, 10, 15, & 16, monumented with an iron post, 2" dia., firmly set, projecting 4" above ground, with a brass cap mkd. WC T19S R8W S 9 S10 S16 S15 1952,  
from which the remains of a BT mkd by Lytle & Norseth in 1952  
A fir snag, 29" dia., bears S.28°W., 27.1 ft., with a healed blaze.

At the corner point

This position now functions as an Angle Point. Remove marks WC S9 S10 and add marks AP 2016 to the cap to now read

AP  
T19S|R8W  
S 16|S 15  
1952  
2016

The cor. of secs. 9 10, 15, and 16, perpetuated by Rice, in 2015, monumented with the remains of the original cor. tree, a decayed fir snag, size indeterminate, with no marks visible, from which the remains of an original BT. (Cont.)

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A decayed fir snag, size indeterminate, bears N.74½°E., 16.5 ft., with scribe marks T19S R8W visible on open blaze.  
and the bearing trees mkd. by Rice  
A fir, 22" dia., bears N.81¾°E., 31.8 ft., with scribe marks R8W visible on partially healed blaze and an aluminum nail right side center.  
A fir, 14" dia., bears S.26¾°E., 5.5 ft., with illegible scribe marks visible on partially healed blaze and an aluminum nail right side center.  
A fir, 16" dia., bears N.1¾°W., 12.7 ft., with illegible scribe marks visible on partially healed blaze and an aluminum nail right side center.  
At the corner point  
Remove fir snag and set a stainless steel post, 28" long, 2½" dia., 27" in the ground, with brass cap mkd.  
T19S R8W  
S 9|S 10  
S16|S15  
2016  
from which a new bearing tree  
A dogwood, 8" dia., bears S.62°W., 10.4 ft., mkd. T19S R8W S16 BT.  
A search was made for all original line trees on the line bet. secs. 15 and 16 and none were recovered.  
NAD 1983 (2011)  
Latitude: 43°55'17.00" N. Longitude: 123°38'20.20" W.

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.