

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 522)

Set post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., mkd: 1/4 S on N face; from which
A Fir, 40" dia., bears S.75°W., 30 lks., mkd: 1/4 S BT
A Fir, 48" dia., bears N.50°E., 13 lks., mkd: 1/4 S BT

BLM dependent resurvey by Lester E. Fisher & David W. Mattson, Cadastral Surveyors, under Group #'s 1000 & 1029, Surveyed Jan/Dec. 1980 - (DCSO records Vol. 46 Page(s) 17720)

The 1/4 sec. cor. of secs. 15 & 22, determined from the remains of the orig. BTs:

A sawed Fir stump, 50" dia., bears N.50°E., 16 lks., with scribe marks 4 S visible on opened blaze. (Rec. 13 lks.)

A Fir, 58" dia., bears S.75°W., 30 lks., with healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T19S R8W
1/4 S 15
S 22
1980

from which a new BT:

A Fir, 18" dia., bears N.25 1/2°E., 17 lks., mkd: 1/4 S15 BT.
Set a 6 ft. steel fence post alongside the iron post.
The corner is located 30 lks., North of graveled road, 25 lks., wide, bears E & W.

Marvin S. Krush, PLS #1643 - For: International Paper - Nov. 11 1982 - M 93-36

CONDITION REPORT ONLY

Found - 1958 BLM BC - (no record found)
48" Fir bears S.75°W., 30 lks. (Orig.)
56" stump bears N.50°E., 16 lks. (Orig.) Partial scribe visible.
19" Fir bears N.25 1/2°E., 17 lks. (existing scribe)