

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 513-4)

-----  
Set post, 4 ft. long, 6" sq., 24" in the ground, for cor. to secs. 22, 23, 26, & 27, mkd: T19S S23 on NE, R8W S26 on SE, S27 on SW, S22 on NW faces, with 2 notches on S & E edges; from which

- A Fir, 24" dia., bears N.12°E., 185 lks., mkd: T19S R8W S23 BT.
- A Fir, 24" dia., bears S.19½°E., 148 lks., mkd: T19S R8W S26 BT.
- A Fir, 12" dia., bears S.14 3/4°W., 212 lks., mkd: T19S R8W S27 BT.
- A Maple, 2" dia., bears N.21°W., 115 lks., mkd: T19S R8W S22 BT.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #'s 350 & 417, Surveyed Sept/Oct 1958 - (DCSO records Vol. 29 Page(s) 12327-8)

-----  
From the corner of secs. 22, 23, 26 & 27, determined at record bearing dist. from each of the remaining Orig. BTs, as follows:

- A Fir, 45" dia., bears N.12°E., 185 lks., with a burned out blaze.
- A Fir snag, 30" dia. bears S.19½°E., 148 lks., with healed blaze; I open & uncover scribe marks T19S R8W S26 BT.
- A decayed Fir stump, 14" dia., bears S.14°45'W., 212 lks., with no marks remaining.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T19S	R8W
S 22	S 23
S 27	S 26
1958	

rom which new BTs:

- A Fir, 8" dia., bears N.29¼°E., 21 lks., mkd: T19S R8W S23 BT.
- A Fir, 9" dia., bears S.45°45'E., 23 lks., mkd: T19S R8W S26 BT.
- A Fir, 10" dia., bears S.35½°W., 8 lks., mkd: T19S R8W S27 BT.
- A Fir, 10" dia., bears N.12½°W., 25 lks., mkd: T19S R8W S22 BT.

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

FD BC & 5 BTs BY D.Baker 4/30/1985 - M 98-55 - C.S. File 58/289-4I
Fd. & used in BLM dependent resurvey by Lester E. Fisher & David W. Mattson, Cadastral Surveyors, under Group #'s 1000 & 1029, Surveyed Jan/Dec 1980 -(DCSO records Vol. 46 Page(s) 17708-9)
Fd. Ok by M. Krush - 11/11/1982 - M 93-36
Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.