

PRIMARY CORNER DESCRIPTION Cor. Secs. 14, 15, 22, & 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 515)

Set post, 4 ft. long, 4" sq., 24" in ground, for cor. to secs. 22, 23, 14, & 15, marked T19S S14 on NE, R8W S23 on SE, S22 on SW, S15 on NW faces, with 3 notches on S and 2 notches on E edges; from which

- A Maple, 24" dia., bears N.85°E., 100 lks., mkd: T19S R8W S14 BT.
- A Maple, 14" dia., bears S.29°E., 92 lks., mkd: T19S R8W S23 BT.
- A Maple, 8" dia., bears S.41°W., 72 lks., mkd: T19S R8W S22 BT.
- A Maple, 24" dia., bears N.18½°W., 51 lks., mkd: T19S R8W S15 BT.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #'s 350 & 417, Surveyed Sept/Oct 1958 - (DCSO records Vol. 29 Page(s) 12328-29)

The cor. of secs. 14, 15, 22, & 23, determined at the record bearing & distance from each of the orig. BTs, as follows:

- A Maple, 44" dia., bears S.76°E., 100 lks., with decayed blaze facing the corner point. (Rec. bearing, N.85°E.)
- A Maple, 42" dia., bears S.24½°E., 92 lks., with a healed blaze facing the corner point; I open and uncover axe marks but no scribe marks on decayed face of blaze. (Rec. bearing S.29°E.)

At the corner point

Set an iron post, 28" long, 2½" dia., 12" in the ground, to solid rock and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

T19S R8W
S 15 S 14
S 22 S 23
1958

from which new bearing trees:

- A Cedar, 10" dia., bears N.76°E., 40 lks., mkd: T19S R8W S14 BT.
- A Cedar, 26" dia., bears S.54½°E., 4 lks., mkd: T19S R8W S23 BT.
- A Fir, 36" dia., bears S.40°W., 72½ lks., mkd: T19S R8W S22 BT.
- A Cedar, 23" dia., bears N.55½°W., 97 lks., mkd: T19S R8W S15 BT.

(Cont. next page)

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Fd. by M. Krush 11/11/1982 M93-39

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.