

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12 only, T19-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 19, 1899 - (DCSO records Vol. 1 Page(s) 273)

-----  
(79.60 chs.) Intersect the old cor. of secs. 1 and 12, which I destroy.

(80.00 chs.) (North) Set a sandstone 12x10x6 ins., 8" in the ground for cor. of secs. 1 and 12, mkd. 5 notches on S. and 1 notch on N. edges; from which

A dead Fir 7" dia., bears N.16°W., 50 lks. dist. mkd. T19S R10W S1 BT.

A dead Fir 14" dia., bears S.40°W., 74 lks. dist. mkd. T19S R10W S12 BT

\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13036-37)

-----  
Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd:

T 19 S  
S 1  
S 12 S 7  
R 10 W R 9 W  
1959

from which

A Fir 27" dia., bears S.46¼°W., 160 lks. dist. mkd. T19S R10W S12 BT.

A Fir 15" dia., bears N.80½°W., 42 lks. dist. mkd. T19S R10W S1 BT.

Fd. OK Sept. 1988 by D. Baker - M 107-1

BLM Resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/May 1991 - (DCSO records Vol. 49 Page(s) 18756)

-----  
Point for the cor. of secs. 1 and 12 only, erroneously reestablished by Tillman, Holm and Brooks in 1957-58, bears N.16°20'W., 0.242 chs. dist., monumented with an iron post 2½" dia., firmly set, projecting 6" above ground, mkd. and witnessed as described in the official record.

(Cont. Next Page)

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 100571

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12 only, T19-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Amended the marks on the brass cap to read AM 1989 1958,  
reset the monument flush with the ground surface, and at the  
true corner point,

Set a stainless steel post 28" long, 2½" dia., 23" in the  
ground with brass cap mkd: T19S

R10W R9W

S 1 S 7  
S 12

1989

from which the bearing trees mkd. by Tillman, etal

A Fir 33" dia., bears N.53½°W., 148 lks. dist. with healed  
blaze.

A Fir 30" dia., bears N.56°W., 52 lks. dist. with healed  
blaze.

Deposit white "DEEP-1" magnetic marker at base of stainless  
steel post.