

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 424)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S8 on N and 17 on S faces; from which
A Fir, 5" dia., bears N.70°E., 75 lks., mkd: ¼ S BT.
A Fir, 5" dia., bears S.46°W., 70 lks., mkd: ¼ S BT.
Old cor. bears East 9 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15460-61)

Point for ¼ sec. cor. of secs. 8 & 17, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
¼ $\frac{S \ 8}{S \ 17}$
T19S R9W
1969

from which
A Hemlock, 10" dia., bears N.15°E., 42 lks., mkd: ¼ S8 BT.
A Hemlock, 10" dia., bears S.7°W., 35½ lks., mkd: ¼ S17 BT

Fd. Ok by D. Baker - Nov. 1991 - M 114-27

Tony Hostetter - For: FIA Timber Partners II - April 2016 - M172-22

Found - 2½" iron pipe with 1969 brass cap, from which
20" hemlock stump, face evident, BLM tag, bears N.15°E., 27.7 ft. to center.
26" hemlock, face evident, BLM tag, bears S.7°W., 23.4 ft to center.
New BTs- 34" Fir, scribed "S8 ¼ BT" BT tag, bears N.84°12'E., 8.7 ft to spike.
23" Hemlock, scribed "S17 ¼ BT" BT tag, bears S.77°22'W., 4.1 ft. to spike.