

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35, (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 369)

The cor. to secs. 34 and 35, established on former survey, which is a Fir post 3 ft.long, 4" sq., set 24" in the ground mkd. T19SS35 on NE.; and R9W S34 on NW. faces, with 2 notches on E. and 4 notches on W. edges; from which

A Fir 22" dia., bears N.55½°E., 20 lks. dist. mkd. T19S R9W S35 BT.

A Fir 16" dia., bears N.5°W., 54 lks. dist. mkd. T19S R9W S34 BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 379)

The Cor. of secs. 34 & 35, which is a decayed Fir post, marked and witnessed as described by the surveyor general, except that no bearing tree is found in sec. 34. The old post is no longer fit for monument, therefore, at exact corner point

Set an iron post 3 ft. long, 2" dia., 27" in the ground for cor. of secs. 34 and 35, T19S R9W, with brass cap marked:

T19S	R9W
<u>S34</u>	<u>S35</u>
T20S	R9W
S	3
1921	

from which

(Old bearing tree) a Fir 30" dia., bears N.55½°E., 20 lks. dist., mkd. T19S R9W S35 BT.

(New bearing tree), a Maple 18" dia., bears N.43°W., 90 lks. dist., mkd. T19S R9W S34 BT.

Fd. OK in BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12457)

Ronald L Rice - For: Oxbow Timber 1 LLC - 4/2016 - M170-76

Found - Rusted GLO 2" iron pipe (brass cap missing) with the following accessories:

53" D.Fir stump bears N.55½°E., 13.2' - no marks

continued next page

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35, (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set - Record 18" Maple N.43°W., - missing
2½"x24" galvanized iron pipe with 2-1/2" brass cap mkd
T19S R9W
S34|S35
T20S R9W
S3
2016
54633LS
over 2" GLO iron pipe and established the
following BTs
16" D.Fir bears N.79°W., 47.3' - blazed, scribed
T19S R9W S34 BT
10" D.Fir bears N.32°W., 27.7' - blazed, scribed
T19S R9W S35 BT
Closing corner S2, S3 BLM brass cap dated 2006 bears
S.88°49'50"E., 53.35'
Steel post adjacent to corner