



PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, T20-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12457)

-----  
The Sec. Cor., on the S. bdy. of sec. 35, T19S R9W, which was remonumented by Mensch in 1921, with an iron post 2" dia., 8" above ground, firmly set, with brass cap mkd. in 1921 from which

A Cedar 28" dia., bears S.81½°E., 54 lks. dist. mkd. T20S R9W S2 BT. (New BT)

A Hemlock 18" dia., bears S.19½°E., 11 lks. dist., plainly blazed and healed. (Thiel BT)

A Fir 36" dia., bears S.81°W., 52 lks. dist., mkd. T20S R9W S2 BT on bark blaze. (Thiel BT)

(the Cor. of secs. 34 & 35, T19-9, bears West, 0.78 chs.)

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23085-6)

-----  
Point for the cor. of secs. 2 & 3 only, determined at record bearing and distance from the remains of a bearing tree mkd. by Tillman and Gawron in 1953-54

A high cedar stump, 30" dia., bears S.81½°E., 35.6 ft., with scribe marks T20S R9W S2 BT visible on partially healed blaze and remains of X at breast height.

At the Corner Point

Set a stainless steel post, 28' long, 2½' dia., 23' in the ground, in a collar of stone, with brass cap mkd.

T 19 S R 9 W

S 35

S 3 | S 2

T20S R 9W

2006

from which

the remains of the orig. BTs, defaced by Chandler in 1899

A cedar stump, 30" dia., bears N.74°E., 24.4 ft., with no scribe marks visible on decayed partially healed blaze. (Record, N.80°E.)

A fir stump, 55" dia., bears N.76°W., 42.2 ft., no marks visible.

and new bearing trees

A fir, 10" dia., bears S.47½°E., 23.6 ft., mkd. T20S R9W S2 BT.

A fir, 9" dia. bears S.30½°W., 7.4 ft. mkd. T20S R9W S3 BT

Deposit a magnet in a white plastic case at the base of the stainless steel post.

continued next page

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 501100

PRIMARY CORNER DESCRIPTION Sec Cor for 2 & 3 only, T20-9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Record of Survey for Roseburg Resources - Robert Ward -  
11/13/2026 - M186-49 -

-----

Found - 2006 BLM brass cap  
30" Cedar stump bears N.74°E. 24.4'. No marks.  
55" fir stump bears N.76°W. 42.2'. No marks.  
12" fir bears S.47½°E. 23.6' healed face.  
9" fir bears S.30½°W. 7.4', dead, healed face.  
New - ⅝" x 30" rebar with 2½" diam alum cap mkd RM1.  
1091LS 2025 with → pointed to corner bears S.24°W.  
15.0' steel post adjacent to reference monument.  
Steel post adjacent to corner.