

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs 25, 26, 35, & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 440)

The cor. of secs. 25, 26, 35, & 36, established on former survey*, which is a basalt stone, 16x8x8 ins., set 12" in the ground, marked with 1 notch on S & E edges; from which

- A Fir, 5" dia., bears N.27°E., 16 lks., mkd: T19S R9W S25 BT.
- A Fir, 10" dia., bears S.77°E., 23 lks., mkd: T19S R9W S36 BT.
- A Fir, 12" dia., bears S.10°W., 13 lks., mkd: T19S R9W S35 BT.
- A Fir, 9" dia., bears N.6°W., 10 lks., mkd: T19S R9W S26 BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13039)

Point for the cor. of secs. 25, 26, 35, & 36, at proportionate distance; there is no remaining evidence of the orig. corner.

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

| | |
|------|------|
| T19S | R9W |
| S 26 | S 25 |
| S 35 | S 36 |
| 1958 | |

from which

- A Fir, 42" dia., bears N.74°E., 39 lks., mkd: T19S R9W S25 BT.
- An Alder, 20" dia., bears S.47°E., 3 lks., mkd: T19S R9W S36 BT.
- A Hemlock, 18" dia., bears S.18°W., 81 lks., mkd: T19S R9W S35 BT.
- A Fir 40" dia. bears N.60°W., 36 lks. mkd: T19S R9W S26 BT

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15431)

The Cor. of secs. 25, 26, 35, & 36, monumented with an iron post, 2½' dia., firmly set, projecting 4" above ground, with properly marked brass cap. (Cont. next page)

| Alias | Description |
|-------|-------------|
| | |
| | |
| | |
| | |

from which
A root hole, bears N.74°E., 39 lks., with a down Fir alongside, 42" dia., with healed blaze.
A root hole, bears S.47°E., 3 lks., with a down Alder alongside, 20" dia., with scribe marks T19S R9W S36 BT visible on bark.
A Hemlock snag, 18" dia., bears S.18°W., 81 lks., with scribe marks T19S R9W S35 BT visible on open blaze.
A root hole, bears N.60°W., 36 lks., with a down Fir alongside, 40" dia., with partially healed blaze.
and new BTs
A Hemlock, 38" dia., N.32¼°E., 65 lks., mkd: T19S R9W S25 BT.
A Fir, 37" dia., bears S.36 3/4°W., 130 lks., mkd: T19S R9W S35 BT.
A Fir, 36" dia., bears N.32½°W., 100 lks., mkd: T19S R9W S26 BT.
No other suitable trees available within limits.

Ron Rice, NW Land Surveying - Jason Collver - May 2012 - C.S. File 65/76-47

Found - 3¼" BLM brass cap on iron pipe, dated 1958
Hemlock snag, 18" dia., bears S.18°W., 81 lks., with scribe marks T19S R9W S35 BT visible on open blaze. (No Evidence)
Hemlock, 38" dia., N.32¼°E, 65 lks., mkd: T19S R9W S25 BT. (Found 41" dia. x 6' high stump with scribing visible. Metal capped)
Fir, 37" dia., bears S.36¾°W., 130 lks., mkd: T19S R9W S35 BT. (Found 41" dia. x 7' high stump with rotted face)
Fir, 36" dia., bears N.32½°W., 100 lks., mkd: T19S R9W S26 BT. (Found 37" dia. X 6' high stump with healed face)

New - 13" D.Fir bears N.66°E., 5.6 ft. blazed, scribed, T19S R9W S25 BT
13" D.Fir bears N.59°W 14.9 ft. blazed, scribed, T19S R9W S26 BT
15" D.Fir bears S.64°W., 13.6 ft. blazed, scribed, T19S R9W S35 BT

Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor Secs 25, 26, 35, & 36

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Eugene Wobbe - Crew: Brad Foster & Matthew Ternyik - 7/7/2017
- C.S. File 65/95-44

Found - 3¼" brass cap (properly mkd) on 2½" iron post with steel post alongside.
38" hemlock now 40" stump with metal cap, scribing visible "T19S R9W S25 BT" bears N.32¼°E., 42.9' - 1968 BT
37" fir now 32" rotting stump with rotted face bears S.36¾°W., 85.8' - 1968 BT.
36" fir now 32" rotting stump with rotted face bears N.32½°W., 66.0' - 1968 BT
13" D.Fir now 14" with healed face bears N.66°E., 5.6' - 2012 BT.
13" D.Fir now 15" with healed face bears N.59°W., 14.9' - 2012 BT.
15" D.Fir now 16" with healed face bears S.64°W., 13.6' - 2012 BT.
New - Set steel fence post with BLM land survey marker sign near corner.
Note - Bearings are based on 1958 BLM survey.

Jerry Estabrook - For: Roseburg Resources Co. - 4/2021 - M179-32

Found - A 2½" iron pipe with 3½" brass cap marked "T19S R9W S26 S25 S35 S36 1958" BLM with steel post alongside
A 41" Hemlock stump with visible scribe bears N.32°15'E., 42.9'.
A 15" Fir with healed face and tag bears N.66°E., 5.6'.
A 30" Fir stump with visible scribe and tag bears S.36°45'W., 85.8'.
A 16" Fir with healed face and tag bears S.64°W., 13.6'.
A 15" Fir with healed face and tag bears N.59°W., 14.9'.
A 34" Fir stump with healed face and tag bears N.32°30'W., 66.0'.
FD B0 - A steel post bears South 3.0'.
LAT and LONG per GARMIN ETREX HAND HELD GPS -
N:43°53'06.5" W 123°43'41.2"