

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T20-10

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Nathaniel Martin, under Contract 599, dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 214)

 Hillside, set post 4 ft. long, 4" sq., 24" in the ground for cor. of secs. 3, 4, 33 and 34, marked T19S R10W S34 on NE.; T20S R10W S.3 on SE.; S4 on Sw.; S33 on NW. faces, with 3 notches on E. and W. edges. No green timber within limits; raised mound of stone around post, 18" high and 30" base. Pits impracticable.

GLO resurvey by Fred Mensch, U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 262)

 "No corners are found between the cor. of secs. 4, 5, 32 and 33, and the cor. which I accept as cor. of Tps. 19 and 20 S., R 10 W., but I find a fairly continuous line of old blazes extending as far as this Tp. cor., but no further eastward.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11683)

 Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
 Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T 19	S R	10	W
S 33		S 34	
S 4		S 3	
T 20 S			
1952			

from which

- A Fir 18" dia., bears N.68°E., 10 lks. dist. mkd. T19S R10W S34 BT.
- A Fir 12" dia., bears S.54°E., 21½ lks. dist. mkd. T20S R10W S3 BT.
- A Fir 12" dia., bears S.22°W., 10 lks. dist. mkd. T20S R10W S4 BT.
- A Fir 14" dia., bears N.28°W., 17 lks. dist. mkd. T19S R10W S33 BT.

Corner report by Ernesto Alvarado, USFS, deputized by DCSO with Wit: Diane Lawson - Nov. 8, 1978 - C.S. File 60/17-24

 Found - 1952 GLO brass cap properly mkd.
 13" D.Fir bears S.26°W., 7.2 ft.
 13" D.Fir bears N.29°W., 11.3 ft.
 (Cont. Next Page)

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T20-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" D.Fir bears S.54°E., 13.8 ft.
17" D.Fir bears N.50°E., 6.4 ft.
CONDITION REPORT ONLY. NO NEW MONUMENT OR ACCESSORIES.
Go down USFS Rd. #48 to section line post for township line.
(Sec. cor. for 32, 33, 4, 5, is just off road) (Sec. cor. for 33, 34, 4 and 3 is one mile East of sec. line post.)
See C.S. File 61/6-9 for 1980 condition report

Fd. OK, June 1982 by W. Shull - M 92-29

Survey by Les Roberts, LS #1039 - For: International paper & US Forest Service - Dec. 1990 - M 111-33

Found - 1952 GLO brass cap.
12" Fir S.53°E., 13.7 ft., scar visible. 1952 BT
13" Fir snag S.25°W., 7.3 ft., scar visible. 1952
14" Fir N.28°W., 10.9 ft., scar visible. 1952 BT
18" Fir N.57°E., 6.4 ft., scar visible. 1952 BT
Set 2½" x 30" alum. pipe and cap for reference monument.
Brass cap bears N.89°42'30", 63.06 ft. from reference monument.

2