

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 289)

The ¼ sec. cor., established on former survey*, which is a Fir tree, 7" dia., mkd: ¼ S33 on W & S34 on E sides; from which

 A Fir, 7" dia., bears N.51°E., 7 lks., mkd: ¼ S BT.

 A Fir, 6" dia., bears S.50°W., 8 lks., mkd: ¼ S BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

Ernest Alvarado, USFS & Dep. Douglas Co. Surveyor - Carol Dickison - 11/2/1978 - C.S. File 60/17-20

Not found.

No evidence of ¼ corner between secs. 33 & 34, T19S R10W was found. There are some new blazed trees going into the area, but could not find any old blaze.

No evidence of BTs or other accessories found. The area has a lot of windfall trees. There are 2 stumps that have been cut into.

Donald Peel, Triangle Eng. Co. - For: USFS - Sept. 1980 - M 85-46

Set - 2½" alum. mon. by single proportionate measure.

 28" Fir bears N.56°E., 42.1 ft.

 28" Fir bears S.75°W., 43.3 ft.