

PRIMARY CORNER DESCRIPTION Cor Secs 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 282-3)

The cor. of secs. 26, 27, 34, & 35, established on former survey*, which is a Fir post, 3 ft. long, 4" sq., 24" in the ground, mkd: T19S S26 on NE, R10W S35 on SE, S34 on SW & S27 on NW faces, with 1 notch on S & 2 notches on E edges; from which

- A Fir, 12" dia., bears N.58°E., 54 lks., mkd: T19S R10W S26 BT.
- A Fir, 12" dia., bears S.70°E., 19 lks., mkd: T19S R10W S35 BT.
- A Fir, 16" dia., bears S.64°W., 18 lks., mkd: T19S R10W S34 BT.
- A Fir, 10" dia., bears N.59°W., 8 lks., mkd: T19S R10W S27 BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

Douglas Co. Surveyors Office - Milo E. Godfrey, - Sept 1964 - C.S. File 53/66-40

Found - Fir snag, N.59°W., 5.3 ft. prev. opened good scribing visible.
42" D.Fir N.58°E., 35.6 ft., shows good scars.
36" D.Fir S.64°W., 11.9 ft., shows good scars.
36" D.Fir S.7°E., not S.70°E., 12.5 ft., shows good scars.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T19S R10W
OFFICE 1964 S 27 | S 26
S 34 | S 35

Rescribe-36" D.Fir S.64°W. 11.9 ft. mkd: T19S R10W S34 CS BT.
36" D.Fir S.7°E., 12.5 ft. mkd: T19S R10W S35 CS BT.
42" D.Fir N.58°E. 35.6 ft. mkd: T19S R10W S26 CS BT.

New BT - 10" Hemlock, N.29°E., 90.0 ft., mkd: T19S R10W S26 CS BT.

Fd. Ok 9/20/1977 - USFS - C.S. File 58/162-4 & M65-63 (Fd. cap stamped in reverse)

(Cont. next page)

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Randy Smith - Nov. 16, 1982 - C.S. File 62/1-28

Found - 1964 Douglas County brass cap firmly set facing South with sec. numbers improperly stamped.
Orig. Fir now 28" stump with scribing visible bears N.59°W., 5.3 ft.
Orig. 42" Fir now 47" with good scar bears N.58°E., 35.6 ft.
Orig. 36" Fir now 39" with good scar bears S.64°W., 11.9 ft.
Orig. 36" Fir now 39" with good scar bears S.7°E., 12.5 ft.
10" Hemlock now 13" with good scar bears N.29°E., 90.0 ft. 1964
Set - Since location of found brass cap is correct but markings wrong, I reference location then reset a new 1"x30" IP with brass cap at orig. location. Cap marked "Douglas Co. Surveyor" T19S S27 S26 S34 S35 R10W Reset 1982 1964.

Fd. & used on BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18781)
Note - Corner is located in a barbed wire fence, bears N-S