

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; & 1, T20-10

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Nathaniel Martin, under Contract 599, dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 216)  
-----  
Set post 4 ft. long, 4" sq., 24" in ground for ¼ sec. cor. mkd. ¼ S on N. face; from which a  
Hemlock 12" dia., bears North, 55 lks. dist. mkd. ¼ S BT.  
Hemlock 9" dia., bears S.73°W., 27 lks. dist. mkd. ¼ S BT

GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 262)  
-----  
"No corners are found between the cor. of secs. 4, 5, 32 and 33, and the cor. which I accept as cor. of Tps. 19 and 20 S., R 10 W., but I find a fairly continuous line of old blazes extending as far as this Tp. cor., but no further eastward."

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11686)  
-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: ¼  $\frac{S\ 36}{S\ 1}$   
1952  
from which  
A Fir 36" dia., bears N.75°E., 60 lks. dist. mkd. ¼ S36 BT.  
A Fir 54" dia., bears S.83°45'E., 79 lks. dist. mkd. ¼ S1 BT.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, & J. Pike crew - May 6, 1992 - C.S. File 64/26-5  
-----  
Found - A 2½" dia. 1952 BLM brass cap on a 1¼" O.D. iron pipe firmly set and protruding approx. 3" above ground.  
A 36" Fir, now a fallen and partially rotted Fir snag, with evidence of a fully healed single blaze, the root hole of which bears N.75°E., 39.6 ft. (as per rec.)  
A 54" Fir now a 45" DBH D.Fir with a fully healed single blaze, bears S.86°E., 53.2 ft. (Rec. S.83°45'E., 52.1 ft.) (previously recorded dia. appears to be erroneous)  
(Cont. Next Page)

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; & S. 1, T20-10

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

New BTs- A 55" DBH 80 ft. tall Fir snag with a high, open  
cruisers blaze bears S.72°W., 57.8 ft.

A 6" DBH Alder bark scribed "¼ S1 CS BT" bears N.86  
¾°W., 30.7 ft. dist.

Monument is on a South slope near bottom of very steep slope.  
Monument on an E-W cutting line with older clear cut to  
North, old growth to South. Monument is approx. 200 ft.  
South from a closed logging spur road end.