

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 7 only, T19-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13036)

Point for the ¼ sec.cor. of sec. 7 only, on the W. bdy. of T19S R9W., at midpoint between closing corners.

Set an iron post 28" long, 2½" dia., 22" in the ground with brass cap mkd:

¼
T 19 S
S 7
R 9 W
1958

from which

A Hemlock 22" dia., bears N.48½°E., 147 lks. dist. mkd. ¼ S7 BT.

A Hemlock 18" dia., bears S.47°E., 77 lks. dist. mkd. ¼ S7 BT.

Survey by Daniel Baker, LS #1978 - For: Margaret Crowell - Sept. 19, 1988 - M 107-1 (See C.S. File 63/69 for Lane Co. information.)

Set U.S.F.S. alum. monument mkd. "T19S ¼ R10W R9W PLS 1978 1988". from which

34" Fir N.48°E., 115.5 ft. BLM BT.

26" Hemlock S.72½°E., 59.1 ft. scribed ¼ S7 BT.

Note: 1/4 Cor. set by BLM in 1958 bears N.37°04'53"E., 74.85 ft.

BLM Resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/May 1991 - (DCSO records Vol. 49 Page(s) 18755)

Point for the ¼ sec. cor. of sec. 7 only, T19S R9W.

From this point, the ¼ sec. cor. erroneously established by Tillman, etal in 1957-58, bears N.29°23'E., 1.029 chs. dist., monumented with an iron post 2½" dia., firmly set, projecting 6" above ground, mkd. and witnessed as described in the official record, except the NE. BT is a Fir, bears N.66½°E., 68 lks. dist. (Rec. Hemlock N.48½°E., 147 lks.), and found no evidence of the SE. BT. Remove the iron post and at the true corner point:

Set a stainless steel post 28" long, 2½" dia., 23" in the ground with brass cap mkd:

T19S
R10W R9W
¼
S 7
1989

(Cont. Next Page)

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 700549

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 7 only, T19-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which
A stainless steel post 28" long, 2½" dia., set 28" in the ground for a reference monument, bears N.29°23'E., 102.9 lks. dist., with brass cap mkd. RM ¼ S7 67.9 FT TO COR 1989 and an arrow pointing to the corner.
and a bearing tree mkd. by Tillman, Holm and Brooks:
A Fir 34" dia., bears N.44°E., 163 lks. dist. with healed blaze.
and a bearing tree mkd. by Baker in 1988:
A Hemlock 25" dia., bears S.68°E., 75 lks. dist. with scribe marks ¼ S7 BT visible on partially healed blaze.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

From this same point, a point established as the ¼ sec. cor. by Baker in 1988, bears S.87°44'W., 0.177 chs. dist., monumented with an alum. post, 2½" dia., firmly set, projecting 6" above ground, with alum. cap mkd. T19S R9W R10W ¼ S7 S1978 1988. This point was established using improper control is is not utilized in this survey.

Removed alum. monument, set rebar. Position change. May 1990, C.S. File 63/104 - D. Baker

Cor. Fd. OK March 1997 by D. Baker - M 124-48