

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35 only, (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by J. H. McClung, under Contract #173, dated July 20, 1872 - (DCSO records Vol. 2 Page(s) 679)

Set post for cor. to secs. 2, 3, 34 and 35; from which
A Fir 6" dia., bears N.49°W., 30 lks.
A Fir 6" dia., bears N.30°E., 70 lks.
A Fir 5" dia., bears S.41°W., 35 lks.
A Fir 5" dia., bears S.18°E., 21 lks.

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 716-17)

Found post much decayed. Set post 6" dia., 4 ft. long, with marked stone 12" in ground, for cor. to secs. 34 & 35, mkd. T20S S35 on NE.; T21S S3 on SE.; R6W S34 on NW.; face, with two notches on E. & 4 on W. edge; from which old bearing trees:
Fir 12" dia., bears N.49°W., 30 lks. dist. mkd. T20S R6W S34 BT.
Fir 12" dia., bears N.30°E., 70 lks. dist. mkd. T20S R6W S35 BT.
Fir 12" dia., bears S.18°E., 21 lks. dist. mkd. T21S R6W S2 BT.
Fir 12" dia., bears S.41°W., 35 lks. dist. mkd. T21S R6W S3 BT.

Ben B. Irving, County Surveyor - Byron; Irving; Fee, crew - April 1954 - C.S. File 45/275 and 41/274

Found the following trees:
48" Fir, N.49°W., 19.8 ft. scribing gone.
48" Fir, S.41°W., 23.1 ft., scribing gone.
48" Fir, N.30°E., 52.0 ft., blazed, not cut out.
Blazed and Scribed the following trees:
8" Cedar S.83°E., 48.5 ft. "S35 T20S R6W CS BT"
14" Cedar N.41°W., 78.0 ft. "S34 T20S R6W

Douglas Co Surveyors Office - Milo E Godfrey, Deputy - Vernon Tracy; C Putnam, crew - Dec. 1961 - C.S. File 49/143-14

Found - Found DCSO brass cap set by Irving in 1954.
20" Cedar, N.41°W., 67.0 ft., not 78.0 ft., scribing visible.
(Cont. Next Page)

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35 only, (South)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>10" Cedar S.83°E., not N.83°E., 48.5 ft., scribing visible. Blaze and scribe: 10" Fir N.31½°E., 57.9 ft. mkd. T20S R6W S35 CS BT. Corner in fence corner. Fences run N. and W. from corner. Original bearing trees all dead and dying.</p>
<p>Fd. OK, Nov. 1983 by Lloyd Smith - M 95-49</p>
<p>Fd. and Used in BLM Resurvey by Wayne L. Rogers, Group #1231, Surveyed Sept. 1984/May 1985 - (DCSO records Vol. 47 Page(s) 18054-55)</p>
<p>Fd. Ok by David Edwards - M 130-31 - 9/1998</p>
<p>BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #2048, surveyed June/July 2003 - (DCSO records Vol. 55 Page(s) 21512-3)</p> <p>-----</p> <p>The cor. of secs. 34 and 35 only, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees A fir stump, 48" dia., bears N.32°E., 52.1 ft., with a healed blaze. A fir, 56" dia., bears S.41°W., 23.1 ft., with a healed blaze. A fir stump, 38" dia., bears N.47¼°W., 20.7 ft., no marks visible on an opened blaze. (Record, N.49°W., 19.8 ft.) and bearing trees mkd. by Irving, in 1954 A cedar, 18" dia., bears S.82°E., 48.2 ft., with a healed blaze. A cedar, 42" dia., bears N.41°W., 67.3 ft., with a healed blaze. and a bearing tree mkd. by Godfrey, in 1961 A fir, 20" dia., bears N.32°E., 58.1 ft., with a healed blaze.</p>
<p>Fd. BC & 5 BTs - Corey Woodruff, 4/2013 - M165-16</p>
<p> </p>