

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 681

Set post for corner to secs. 25, 26, 35 & 36; from which
A Fir, 7" dia., bears N.24°W., 40 lks.
A Fir, 8" dia., bears S.88°W., 44 lks.
A Fir, 24" dia., bears N.55°E., 50 lks.
A Fir, 12" dia., bears S.40°E., 20 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - Clete Putman - June 5, 1961 - C.S. File 49/89-12

Found - ½" IP at corner.
Orig. 12" now 18" Fir snag S.40°E., 13.2 ft. shows good scribing S36.
Orig 8" now 14" down Fir S.88°W. 33.0 ft not 29.4 ft
No trace of orig. NW & NE BTs found. We opened SW BT & found good scribing.
Set - Brass cap alongside ½" pipe & mkd: S26|S25 T20S R6W
County Surveyors Office, 1961 S35|S36
16" R.Fir bears S.21°E., 54.0 ft. scribed S36 T20S R6W CS BT.
5" R.Fir bears S.79°W., 28.3 ft. scribed S35 T20S R6W CS BT.
22" R.Fir bears N.48°W., 29.6 ft. scribed S26 T20S R6W CS BT.
No trees near to NE.

David C. Wellman, for Weyerhaeuser Co. July 1994 - M120-55

CONDITION REPORT ONLY

Found - ¾" Iron Pipe w/Douglas County Brass Cap dated 1961.
18" Fir snag, S.38°E., 14.0 ft. - visible scribing.
- rec. S.40°E., 20 lks. - 1872 O.B.T.
- rec. S.40°E., 12.7 ft. to "W" nail - 1957 Weyerhaeuser.
37" Fir stump, N.34°E., 35.9 ft. - rec. N.29°E., 34.3 ft. to "W" nail - 1957 Weyerhaeuser.
18" Fir, S.78°W., 28.3 ft. - rec. S.78°W., 28.0 ft. to "W" nail - 1957 Weyerhaeuser.
- rec. S.79°W., 28.3 ft. - 1961 Douglas County.
29" Fir, N.41°W., 29.0 ft. - closed face. - rec. N.49°W. 28.9 ft. to "W" nail - 1957 Weyerhaeuser.
- rec. N.48°W., 29.6 ft. - 1961 Douglas County.
27" Fir, S.21°E., 54.1 ft. - closed face. - rec.S.21°E., 54.0 ft. - 1961 Douglas County.

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

FD. Ok by L. Roberts 4/1996 - M 123-60

BLM dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1839 surveyed May 1997 - (DCSO recs. Vol. 53 Pg(s) 20370-1)

The cor. of secs. 25, 26, 35, & 36, perpetuated by Byron, in 1961; monumented with an iron post, 1¼ ins. diam., firmly set, projecting 14" above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 20 S R 6 W

S 26 | S 25

S 35 | S 36

1961

from which the remains of an original bearing tree

A decayed fir stump, size indeterminate, bears S.40°E., 20 lks., no marks visible.

and the remains of bearing trees mkd. by Byron

A fir, 28" dia., bears S.22°E., 81 lks., with healed double blaze.

A fir, 19" dia., bears S.78½°W., 42½ lks., with healed blaze.

A fir, 28" dia., bears N.47½°W., 44½ lks., with healed blaze.

and the remains of a reference tree by Weyerhaeuser Co., (determined from a "W" nail driven in at base)

A sawed fir stump, 40" dia., bears N.30½°E., 52 lks. to head of a nail at the base, mkd. W.

and a new bearing tree

A fir, 12" dia., bears N.59¼°E., 26½ lks., mkd. T20S R6W S25 BT.

From this point, the Bureau of Land Management Geodetic Control Station No. EC 41004, at latitude 43°47'27.995"N., longitude 123°23'16.915"W. (NAD 1983), determined by the NAVSTAR Global Positioning System, bears S.77°10'12"W., 80.045 chs. (mean bearing and sea level); monumented with an aluminum cap, 3¼" dia., firmly set flush with the ground in concrete, mkd. EC 41004 GPS 1989.

Fd. & uses on BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #2048, surveyed June/July 2003 - (DCSO records Vol. 55 Page(s) 21514-5)