

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 682

Set post for ¼ sec. cor. in edge of green timber, course NE & SW; from which

A Maple, 7" dia., bears S.35½°W., 40 lks.

A Laurel, 4" dia., bears S.55°E., 15 lks.

Douglas Co. Surveyors Office - Milo Godfrey - Feb. 1962 - C.S. File 49/89-38

Reported as searched for & not found.

BLM dependent resurvey by William W. Glenn, Cadastral Surveyor under Group #441 dated May 1962, surveyed June/July 1962 - (DCSO records Vol. 27 Page(s) 11324C)

Point for ¼ sec. cor. of secs. 24 & 25, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T 20 S R 6 W

¼ S 24

S 25

1962

from which

A Fir, 18" dia., bears N.5°E., 31 lks., mkd: ¼ S24 BT.

A Fir, 20" dia., bears S.44°W., 31½ lks., mkd: ¼ S25 BT.

BLM dependant resurvey by Daniel N. Patterson & Craig Wanless, Cadastral Surveyors, Under group #1764 dated Jan. 1995, surveyed Jan./May 1995 - (DCSO records Vol. 52 Page(s) 19701 & 2)

Point for the ¼ sec. cor. of secs. 24 & 25, at proportionate distance, there is no remaining evidence of the orig. corner. Set a stainless steel post, 28 ins. long, 2½" diam., 24 ins. in the ground, with brass cap mkd.

T 20 S R 6 W

¼ S 24

S 25

1995

from which new bearing trees

A fir, 11" diam., bears N.14½°W., 59½ lks., mkd. ¼ S24 BT.

A fir, 12" diam., bears S.79½°W., 107 lks., mkd. ¼ S25 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, the $\frac{1}{4}$ sec. cor. of secs. 24 & 25, erroneously reestablished by Glenn in 1962, bears S. $1^{\circ} 29'$ W., 0.116 chs. dist.; monumented with an iron post, $2\frac{1}{2}$ " diam., firmly set, projecting 3" above ground, with brass cap mkd. and witnessed as described in the official record, except there is no remaining evidence of the SW. bearing tree. Remove the marks from the 1962 brass cap and remark the brass cap AM 7.66 FT 1995 and an arrow pointing toward the corner, no marks were removed from the NE. bearing tree due to its size and condition.

From this same point, the Bureau of Land Management Geodetic Control Station No. 41238, established in 1995 at latitude $43^{\circ}48'59.949''$ N., longitude $123^{\circ}22'28.057''$ W. (NAD 1983(91), bears N. $57^{\circ}09'00''$ W., 77.795 chs. (mean bearing and sea level dist.); monumented with an aluminum rod, $\frac{3}{4}$ in. diam., firmly set flush with the surface of the ground, with aluminum cap mkd. EC 41238 1995.