

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec Cor for 25 & 36; 30 & 31, T20-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 677)

-----  
Set post corner of secs. 25, 30, 31 and 36; from which  
A R.Fir 9" dia., bears S.10°W., 11 lks. dist.  
A R.Fir 20" dia., bears S.17°E., 8 lks. dist.  
A R.Fir 9" dia., bears N.58°E., 31 lks. dist.  
A R.Fir 40" dia., bears N.3°W., 65 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; C.Putnam, crew - Jan. 1962 - C.S. File 49/89-10

-----  
Found - Orig. 9" Fir, now 35", N.58°E., 20.5 ft., cut open and find good scribing "S". Tree in very good condition.  
Burned remains of old Fir snag, N.3°W., 42.9 ft. No scars or scribing found.  
Fir tree, now 40" S.17°E., 5.3 ft., uprooted and down, shows good scar.  
Rotted remnants of SW. BT, found good reverse scribing visible. Impossible to determine where tree had stood.

Set Brass cap at cor. mkd: County Surveyors Office

T 20 S  
S 25 | S 30  
S 36 | S 31  
R 6 W R 5 W  
1962

New BTs- 17" D.Fir N.50°W., 37.8 ft. mkd. T20S R6W S25 DCS BT  
8" I.Cedar S.56½°W., 11.1 ft. mkd. T20S R6W S36 DCS BT.  
40" D.Fir S.18½°E., 48.3 ft. mkd. T20S R5W S31 DCS BT.

Corner Fd. OK in BLM Resurvey by Brooks and Kent, under Group #648, Surveyed Aug 1967/Sept. 1971 - (DCSO records Vol. 37 Page(s) 15268)

-----  
Added the marks BLM 1967 to the brass cap.  
Corner point is located on top of ridge, divides Smith River and Siuslaw River drainages, bears N.40°E. and S.10°W.

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec Cor for 25 & 36; 30 & 31, T20-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1839 surveyed May 1997 - (DCSO recs. Vol. 53 Pg(s) 20369)

-----  
Beginning at the cor. of secs. 25, 30, 31, and 36, on the E. bdy. of the Tp., monumented with an iron post, 1¼" diam., firmly set, projecting 2" above the ground in the root wad of an original bearing tree, with brass cap mkd.

DOUG. CO. SURVEYORS OFFICE

T 20 S  
S 25 | S 30  
S 36 | S 31  
R 6 W R 5 W  
BLM 1967  
1962

from which the remains of original bearing trees

A sawed fir stump, 36" diam., bears N.58°E., 31 lks., with healed blaze.

A roothole, bears S.17°E., 8 lks., with down fir alongside, 36" diam., no marks visible.

A burned fir stump, size indeterminate, bears N.3°W., 65 lks., with partially decayed trunk alongside, no marks visible.

and the remains of BTs mkd. by Godfrey, in 1962,

A sawed and capped fir stump, 37" diam., bears S.19 3/4°E., 73 lks., with healed double blaze.

A cedar, 19" diam., bears S.57¼°W., 16½ lks., with healed double blaze.

A fir, 25" diam., bears N.49½°W., 56 lks., with healed double blaze. (Record, 58 lks.)

and new bearing trees

A fir, 7" diam., bears N.66½°E., 27½ lks., mkd. T20S R5W S30 BT.

A cedar, 13" diam., bears S.62½°E., 45½ lks., mkd. T20S R5W S31 BT.

The corner is located N., 1.15 chs. dist. of a ridge, bears N.40°E. and S.40°W.