

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 622)

-----  
Set sandstone, 12x10x5" 8" in the ground for the 1/4 sec. cor. marked 1/4 on W face; from which

A fir, 50" dia., bears S.26°W., 6 lks., mkd: 1/4 S BT.

A fir, 24" dia., bears N.28°W., 42 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Lynn M. Roseberry & Wm. W. Glenn, Cadastral Surveyors, under Group #350 & 622, surveyed Oct. 1966/May 1967 (DCSO rec. Vol. 34 Page(s) 14147)

-----  
The 1/4 sec. cor. of secs. 19 & 30, monumented with the orig. burned & shattered sandstone, size indeterminate, with faint chisel marks visible, from which the orig. BTs:

A burned fir, 31" dia., bears N.28°W., 42 lks., with a portion of orig. scribe marks visible on burned out blaze & rescribed 1/4 S19 BT on new blaze.

A burned fir, 50" dia., bears S.26°W., 6 lks., with a portion of orig. scribe marks visible on burned out blaze & rescribed 1/4 S30 BT on new blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:

T20S R7W  
1/4  $\frac{S\ 19}{S\ 30}$   
1966

Deposit the orig. corner stone alongside & a quart jar at the base of the iron post.

Set a steel fence post alongside the iron post.

No live BTs available within limits.

Ronald L Rice - For: Oxbow Timber 1 LLC - Sept 2015 - M170-15A&B

-----  
Found - GLO brass cap dated 1966

31" D.Fir stump bears N.28°W. 27.7' scribing visible

50" D.Fir stump bears S.26°W., 4.0' axe work visible

New BTs- 18" D.Fir bears N.38°W. 17.9' blazed, scribed 1/4 S19 BT

17" D.Fir bears N.68°E. 14.3' blazed, scribed 1/4 S19 BT

17" D.Fir bears S.86°E. 11.5' blazed, scribed 1/4 S30 BT

17" D.Fir bears S.54°W. 13.6' blazed, scribed 1/4 S30 BT

Steel post adjacent to corner.