

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 621)

Set sandstone, 20x10x6" 16" in the ground for the 1/4 sec. cor. marked 1/4 on W face; from which
A fir, 30" dia., bears N.84°E., 8 lks., mkd: 1/4 S BT.
A fir, 50" dia., bears S.59°W., 100 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Lynn M. Roseberry & Wm. W. Glenn, Cadastral Surveyors, under Group #350 & 622, surveyed Oct. 1966/May 1967 (DCSO rec. Vol. 34 Page(s) 14145)

Point for 1/4 sec. cor. of secs. 29 & 30, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:

T20S R7W
1/4
S 30 | S 29
1966

from which
A burned fir, 20" dia., bears S.39 1/2°E., 142 lks., mkd: 1/4 S29 BT.
A burned fir, 62" dia. bears N.75°W. 59 lks. mkd: 1/4 S30 BT
Set a steel fence post alongside the iron post.

Ronald Rice - For: Oxbow Timber 1 LLC - Sept. 2015 - M170-15A&B

Found - BLM brass cap dated 1966
20" Fir staub bears S.39 1/2°E., 93.7' - no marks
62" D.Fir stump bears N.75°W., 38.9' - no marks
New - 16" D.Fir bears S.66°E., 33.0' - blaze, scribed 1/4 S29 BT
19" D.Fir bears N.48°E., 22.5' - blaze, scribed 1/4 S29 BT
21" D.Fir bears N.56°W., 25.3' - blaze, scribed 1/4 S30 BT
18" D.Fir bears S.36°W., 15.4' - blaze, scribed 1/4 S29 BT
Steel post adjacent to corner.