

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 608)</p> <p>-----</p> <p>Set post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on W face; from which</p> <p> A fir, 48" dia., bears S.17°E., 23 lks., mkd: ¼ S BT.</p> <p> A cedar, 12" dia., bears N.72°W., 10 lks., mkd: ¼ S BT.</p>
<p>Wilford N. Haines - For: Woolley Logging - 1961 - C.S. File 51/222 & M21-76</p> <p>-----</p> <p>Found - Scribed stake</p> <p> 48" Fir N.73°E., 23 lks.</p> <p> 12" Cedar N.72°W., 10 lks.</p> <p>Set - 1"x1"x36" T iron.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Clete Putnam - May 1962 - C.S. File 49/89-34</p> <p>-----</p> <p>Found - Haines "T" iron at corner - Also real old, rotten square stake, could be orig.</p> <p> 48" Fir N.73°E., (instead of S.17°E.) 15.2 ft. Fir is down & badly rotted, good scribing visible</p> <p> "¼SBT" would be facing cor. if tree was standing.</p> <p> Remains of cedar stump N.72°W., 6.6 ft. not enough left to find scribing.</p> <p>New BTs- 42" R.Cedar N.71°E., 23.0 ft., mkd: ¼ S33 CS BT</p> <p> 17" Hemlock N.78°W., 37.4 ft., mkd: ¼ S32 CS BT</p> <p>Note - Orig. call on top of spur was in error by approx. 10 chs.</p> <p> DID NOT SET BRASS CAP.</p>
<p>Wilford N. Haines - Nov. 1965 - C.S. File 51/309-3</p> <p>-----</p> <p>Found - "T" iron</p> <p> R.Cedar stump scribed by Co. Surv. N.72°E., 23.0 ft.</p> <p>New BT - 14" Hemlock N.61°W., 165.9 ft.</p>
<p>BLM Dependent resurvey by Wayne Rogers & Lance J. Bishop, Cadastral Surveyor, under Group #1159, surveyed Aug.1983/ May 1984 - (DCSO records Vol. 47 Page(s) 18042-3)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 33 & 34, perpetuated & recorded by Haines in 1961 & 1965, and further perpetuated & recorded by Godfrey in 1962, monumented with a 1" "T" shaped iron rod, firmly set, projecting 4" above ground, from which the remains of an OBT: continued next page</p>

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A roothole, bears N.70°E., 23 lks., with a down fir alongside, size indeterminate, no marks visible (Rec. S.17°E.,)
and the remains of a BT mkd. by Godfrey
A sawed cedar stump, 40" dia., bears N.68°E., 36 lks., with scribe marks ¼ S33 BT visible on open double blaze.
and the remains of a BT mkd. by Haines in 1965
A hemlock snag, 26" dia., bears N.62°W., 249 lks with healed blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, directly over the iron, with brass cap marked:
T20S R7W
 ¼
 S 32|S 33
 1984
from which new BTs
A fir, 8" dia., bears N.58°E., 37½ lks., mkd: ¼ S33 BT.
A fir, 6" dia., bears N.40°W., 30½ lks., mkd: ¼ S BT.

BLM Dependent Retracement by A Bert Skeesick, Cadastral Surveyor Under Group No. 2500, Surveyed May 2012 - DCS0 records BLM Plat 2013-1, T20-7 & Vol. 58 Page(s) 22950

The ¼ sec. cor. of secs. 32 and 33, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.
from which the remains of a BT mkd. by Godfrey, in 1962
A burnt, hollow cedar snag, 36" dia. bears N.68°E. 23.8 ft with fragmentary scribe marks visible on an open blaze.
and remains of a BT mkd. by Homes in 1965
A decayed hemlock stump, size indeterminate, bears N.62°W. 164.3 ft., with no marks visible.
and remains of BTs mkd. by Rogers and Bishop
A fir, 16" dia., bears N.58°E., 24.8 ft., with a healed blaze.
A roothole bears N.40°W., 20.1 ft., alongside of which is a fallen, decayed fir snag, 6" dia., with no marks visible on a partially healed blaze.
and new bearing tree
A fir, 11" dia., bears N.29°W., 40.6 ft. a mkd. ¼ S32 BT.

FD by R. Rice 3/2016 by R. Rice