

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 615)

This point falling on edge of a bluff of rock, 40 ft. wide, 7 ft. high, with a course N.46°E., I mark a cross (x) at exact spot for ¼ sec. cor. marked ¼ S on W face; from which
A fir, 12" dia., bears N.26°E., 10 lks., mkd: ¼ S BT.
A fir, 20" dia., bears S.40°W., 18 lks., mkd: ¼ S BT.

BLM dependent resurvey by Lynn M. Roseberry & Wm. W. Glenn, Cadastral Surveyors, under Group #350 & 622, surveyed Oct. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14154)

The ¼ sec. cor of secs. 8 & 9, falls on the edge of a rock outcrop, 40 ft. long, 7 ft. high, bears N.46°E., mkd. with a faint cross at the exact cor. point, alongside of which is marked ¼, from which the remaining orig. BT:

A rotted fir stump, 12" dia., bears N.26°E., 10 lks., no marks visible.

At the corner point

Set an iron post, 8" long, 1" dia., 7" in a drill hole in solid rock, with brass cap marked:

T20S R7W

¼
S 8 | S 9

1967

from which new BTs

A sawed fir stump, 23" dia., bears N.27°E., 41½ lks., mkd: ¼ S9 BT.

A sawed fir stump, 27" dia., bears S.43°W., 85½ lks., mkd: ¼ S8 BT.

Set a steel fence post alongside the iron post.

Ronald L. Rice - For: Oxbow Timber 1 LLC - May 2014 - M168-5

Found - 1967 BLM brass cap with the following accessories;
23 D.Fir stump bears N.27°E., 27.4' rotted face
27 D.Fir stump bears S.43°W., 56.4' rotted face

New BTs- 15" D.Fir bears S.51°W., 8.0' scribed "¼ S8 BT"
15" D.Fir bears S.10°E., 36.5' scribed "¼ S9 BT"
13" D.Fir bears N.23°E., 17.0' scribed "¼ S9 BT"
15" D.Fir bears N.11°W., 16.3' scribed "¼ S8 BT"
Steel post adjacent to corner