

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 617)

Set post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on W face; from which
A fir, 30" dia., bears N.52°E., 38 lks., mkd: ¼ S BT.
A fir, 36" dia., bears S.88°W., 16 lks., mkd: ¼ S BT.

BLM dependent resurvey by Harvey E. Wofford & Lester E. Fischer, Cadastral Surveyors under Group #913, surveyed Aug. 1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16123-4)

The ¼ sec. cor. of secs. 4 & 5, determined from the remains of the orig. BTs:

A root hole, bears N.52°E., 38 lks., with a down & decayed fir stump alongside, 36" dia., no marks visible.

A root hole, bears s.88°W., 16 lks., with a down fir alongside, 48" dia., with scribe marks ¼ S visible on opened blaze.

At corner point

Set an iron post, 28" long, 2½" dia., 20" in the ground, with brass cap marked:

T20S R7W
¼
S 5 | S 4
1977

No suitable trees available within limits.

Set a 5 ft. steel fence post alongside iron post.

BLM dependent resurvey by Daniel N. Patterson, Cadastral Surveyor under Group No. 2165, surveyed July 2007/Sept. 2008 - (DCSO records Vol. 56 Page(s) 22209)

The ¼ sec. cor. of secs. 4 and 5, remonumented by Wofford and Fischer in 1976-78; monumented with an iron post, 2½" dia., firmly set, projecting 2" above the ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A root hole, bears S.88°W., 10.6 ft., alongside of which is lying a decayed fir, size indeterminate, no marks visible.

and new bearing trees

A fir, 11" dia., bears S.79°E., 14.4 ft., mkd. ¼ S4 BT.

A fir, 13" dia., bears N.15¼°W., 9.0 ft., mkd. ¼ S5 BT.