

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Thos. Todd, under Contract #574, dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 564-65)

-----  
(I here set a cor. common to 4 sections, but after I found the errors in the E. bdy of the township, through which I found it necessary to set closing corners on the N. bdy. of the township, thus making this corner, common to 2 sections each, I returned to this corner and)

Set a Maple post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 32 & 33, marked T19S R7W on N.; S32 on W.; S31 on E. faces, with 4 notches on E. & 2 notches on W. faces; from which

A Fir 40" dia., bears N.12°E., 47 lks. dist. mkd. T19S R7W S33 BT.

A Fir 36" dia., bears N.26°W., 14 lks. dist. mkd. T19S R7W S32 BT.

A Fir 48" dia., bears S.12°W., 45 lks. dist. mkd. T19S R7W S32 & 33 BT.

BLM Resurvey by Norman Price and Thomas Tillman, Cadastral Engineers, under Group #284, Surveyed June/Sept. 1949 - (DCSO records Vol. 31 Page(s) 13008)

-----  
The cor. of secs. 32 and 33, monumented with the decayed remains of the original corner post, from which the original bearing trees:

A Fir 48" dia., bears N.78°E., 45 lks. dist., plainly blazed and healed. (Rec. brg. N.12°E., the complement of the actual bearing; rec. dist. 47 lks.)

A Fir 24" dia., bears S.15°W., 41 lks. dist., with partial scribe marks visible on bark. (Rec. dia., 48"; rec. brg. S.12°W.; rec. dist. 45 lks.)

A Fir 50" dia., bears N.26°W., 14 lks. dist., plainly blazed and healed.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T 19 S R 7 W

S 32 | S 33

T 20 S R 7 W

S 4

1949

Deposit the remains of the original post at base of iron post.

(Cont. Next Page)

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 308700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 only, T19-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Resurvey by Harvey E. Wofford & Lester E. Fischer,  
Cadastral Surveyors, under Group #913, Surveyed Aug.  
1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16100)

-----  
The Sec. cor., monumented with an iron post 2" dia., firmly  
set, projecting 12" above ground, with brass cap mkd. in  
1949, from which the remains of the original bearing trees:  
A sawed Fir stump 24" dia., bears S.15°W., 44 lks. dist.,  
with healed blaze. (Rec. 41 lks.)  
A sawed Fir stump 52" dia., bears N.26°W., 14 lks. dist.,  
with healed blaze.  
No suitable trees available within limits.  
Set a 5 ft. steel fence post alongside iron post.

Survey by Daniel Baker PLS #1978 - For: International Paper  
Co. - Feb. 1984 - M 96-41 and C.S. File 58/289-2D

-----  
Found - 2" I.P. with GLO brass cap "1949".  
23" Fir stump bears S.17°W., 27.3 ft. (Rec. S.15°W.,  
41 lks.)  
55" Fir stump bears N.29°W., 10.5 ft. (Rec. N.26°W.,  
14 lks.)  
New BTs- 8" Fir bears N.53°W., 25.4 ft. scribed T19S R7W S32  
BT.  
7" Fir bears N.2°W., 12.4 ft. scribed T19S R7W S32  
BT.  
No suitable tree in NE. quadrant.