

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Thos. E. Todd under Contract No. 574 dated  
May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 616)

-----  
Set sandstone 18x12x10", 12" in the ground for ¼ sec. cor.  
mkd. ¼ on N face, from which

A cedar, 14" dia., bears N.40°W., 18 lks., mkd: ¼ S BT.

A cedar, 30" dia., bears S.10°E., 30 lks., mkd: ¼ S BT.

Ronald L. Rice - For: Oxbow Timber 1 LLC - May 2014 - M168-5

-----  
No evidence of the ¼ cor. was recovered. The missing ¼ cor.  
was set at proportionate position based the 1892 GLO rec  
Set - 2½" Dia. alum. cap on 5/8"x30" rebar marked as shown

with the following accessories;

20" D.Fir bears N.76°W., 9.8' scribed "¼ S4 BT"

14" D.Fir bears N.71°E., 12.9' scribed "¼ S4 BT"

12" D.Fir bears S.51°E., 16.7' scribed "¼ S9 BT"

18" D.Fir bears S.16°W., 21.4' scribed "¼ S9 BT"

Steel post adjacent to corner

T2OS R7W

¼ S4  
S9

2014

54633LS