

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 603)

-----  
Set charred chinquapin post, 4 ft. long, 4" square, 24" in the ground, for cor. to secs. 15, 16, 21 & 22, marked T20S S15 on NE R7W S22 on SE, S21 on SW, S16 on NW faces, with 3 notches on S & 3 on E edges; from which

- A fir, 30" dia. bears N.6°E., 14 lks. mkd: T20S R7W S15 BT
- A fir, 40" dia. bears S.13°E. 157 lks. mkd:T20S R7W S22 BT
- A fir, 36" dia. bears S.22°W. 173 lks. mkd:T20S R7W S21 BT
- A fir, 50" dia. bears N.75°W. 275 lks. mkd:T20S R7W S16 BT

BLM dependent resurvey by Lynn M. Roseberry & Wm. W. Glenn, Cadastral Surveyors, under Group #350 & 622, surveyed Oct. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14140)

-----  
The cor. of secs. 15, 16, 21 & 22, determined at record bearing & distance from the remains of the orig. BTs:

- A rotted & burned fir stump, 30" dia., bears N.6°E., 143 lks., no marks remaining.
- A rotted & burned fir stump, 40" dia., bears S.13°E., 157 lks., no marks remaining.
- A rotted & burned fir stump, 36" dia, bears S.22°W., 173 lks, no marks remaining.
- A burned out fir stump hole, bears N.75°W., 275 lks.

At corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T20S R7W  
S 16|S 15  
S 21|S 22  
1966

from which new BTs

- A Fir, 37" dia. bears N.27°E. 48½ lks. mkd T20S R7W S15 BT
  - A Fir, 34" dia. bears S.26°E. 76 lks. mkd: T20S R7W S22 BT
  - A Fir, 40" dia., bears S.17½°W., 73½ lks., mkd: T20S R7W S21 BT.
  - A Fir, 38" dia. bears N.70°W. 85 lks. mkd: T20S R7W S16 BT
- Set a steel fence post alongside the iron post.