

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 30 only, T20-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by J. H. McClung, under Contract #173, dated July 20, 1872 - (DCSO records Vol. 2 Page(s) 547)

Set ¼ sec. post, from which
A Fir 16" dia., bears S.57½°W., 9 lks.
A Fir 12" dia., bears S.44°E., 20 lks.

GLO resurvey by Thos. Todd, under Contract #574 dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 583)

Old ¼ sec. cor. to sec. 30, which is a post, firmly set in the ground 3" dia., mkd. ¼ S on W. face; from which
A Fir 12" dia., bears S.44°E., 20 lks. dist. mkd. ¼ S BT.
A Fir 16" dia., bears S.57½°W., 9 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; C Putnam, crew - Jan. 1962 - C.S. File 49/89-27

Found - Old Fir stump 26", S.57½°W., 5.9 ft., chopped open old scar and found good scribing "S".
Rotted base of stump and roots of Fir, S.44°E., 13.2 ft.

Set Brass cap at cor. mkd: County Surveyors Office
T20S R6W W ¼ | S30
1962

New BTs- 6" D.Fir S.10°E., 25.7 ft. mkd. ¼ S30 CS BT.
8" D.Fir N.31°E., 24.7 ft. mkd. ¼ S30 CS BT.

Donald Peel - For: Weyerhaeuser Co. - June 1991 - M 113-45

Found - 1½" Iron pipe with DCSO brass cap dated 1962.
24" Fir N.34°E., 25.0 ft., closed face.
22" rotten Fir stub, S.62°W., 7.1 ft., previously opened to visible scribing. (Rec. S.57½°W.)
16" Fir S.08½°E., 25.7 ft. closed face, BLM tag. Not of record.

Rob Ward - For: Roseburg Resources Co. & Seneca Jones Timber Co. - 3/2001 - M 136-60 & C.S. File 65/36-17 A-L

Found - 2½" DCSO brass cap, dated 1962
24"x4' D.Fir stump bears N.34°E., 25.0' healed face.
16"x5' D.Fir stump bears S.8½°E., 25.7' healed face.
22"x4' D.Fir stump S.62°W., 7.1' opened face, visible scribe.

New BT - 20" Maple bears S.14°W., blazed, scribed at base "X BT"