

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 19 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed fir stump, 40" dia., bears N.88½°E., 70.6 ft., with no marks visible on partially healed blaze.
A hemlock stump, 33" dia., bears S.56°E., 16.5 ft., with a healed blaze.
and new bearing trees
A fir, 12" dia., bears N.19¼°E., 54.2 ft., mkd. ¼ S19 BT.
A fir, 19" dia., bears S.74¼°E., 83.7 ft., mkd. X BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

BLM dependent resurvey by Edith M Forkner and Aaron M. Graham, Cadastral Surveyors, under Group #2312, surveyed July/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22967)

The ¼ sec. cor. of secs. 19 only, on the W. bdy. of the Tp., monumented with an iron post, 1 in. diam., firmly set, projecting 3 ins. above ground, with a brass cap mkd. and accessories as described in the 2005 official survey by Graham.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 9/21/2021 (filed 3/21/2023) - C.S. File 67/55-49

Reported as not found.
Found as described in 2005 & 2011 BLM recoveries. Add BLM tie to CC for 24/25 T20S, R09W S.0°34'18"W., 51.35 ft.