

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 494)

-----  
Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on N face; from which  
Maple, 36" dia., bears N.22°W., 67 lks., mkd: ¼ S BT.  
Fir, 30" dia., bears S.67°E., 34 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A Tillman, Raymond M. Bicknell, Han W. Thielsen & Joseph S. Gawron, Cadastral Engineers, under Group No. 305 surveyed Aug. 1953 thru Sept. 1954 - (DCSO recs. Vol. 29 Page(s) 12384)

-----  
The ¼ sec. cor. of secs. 18 & 19, determined at rec. dist. from the orig. BTs:

A maple, 42" dia., bears N.20¼°W., 67 lks., marked with a healed blaze. (Rec. bearing N.22°W.)

A fir, 50" dia., bears S.64°E., 34 lks., with the mark 9 remaining on the bark. (Rec. bearing S.67°E.)

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼  $\frac{S\ 18}{S\ 19}$   
1954

from which new BTs

A cedar, 32" dia., bears N.38½°W., 104 lks., mkd: ¼ S18 BT

A cedar, 40" dia., bears S.73°E., 38 lks., mkd: ¼ S19 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16749-50)

-----  
The ¼ sec. cor. of secs. 18 & 19, monumented with an iron post, 1" dia., lying on the top of the ground, with brass cap (properly) mkd.

and the remains of the BT marked in 1954

A cedar, 43" dia., bears S.73°E., 38 lks., with fragmentary scribe marks visible on partially healed blaze.

A cedar, 38" dia., bears N.38½°W., 104 lks., no marks remaining on burned blaze. Rescribed ¼ S18 BT on new blaze.

At the corner point

Reset the iron post, 26" in the ground.

Set a 5 ft. steel fence post alongside the iron post.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2000, surveyed Jan./March 2005 - (DCSO rec. Vol. 55 Page(s) 21774-5)

-----  
The 1/4 sec. cor. of secs. 18 and 19, monumented with an iron post, 1" dia., firmly set, 4" below the ground, with brass cap (properly) mkd.

from which the remains of bearing trees mkd. by Tillman, et al., in 1953-54

A cedar stump, 46" dia., bears S.73°E., 25.1 ft., with no marks visible on burned partially healed blaze.

A cedar stump, 33" dia., bears N.38½°W., 68.6 ft., no marks visible.

and new bearing trees

A fir, 9" dia., bears S.2°W., 14.2 ft., mkd. 1/4 S19 BT.

A fir, 15" dia., bears N.48°W., 19.7 ft., mkd. 1/4 S18 BT.

There is a steel fence post alongside the corner.

Each new bearing tree has a 2½"x 1/4" magnetic nail (Mag Nail) driven at the base right side-center.

BLM dependent resurvey by Edith M Forkner and Aaron M. Graham, Cadastral Surveyors, under Group #2312, surveyed July/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22965-6)

-----  
The 1/4 sec. cor. of secs. 18 & 19, monumented with an iron post, 1" dia., firmly set, projecting 5" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs mkd. by Tillman, et al., in 1953-54

A cedar stump, 39" dia., bears S.73°E., 25.1 ft., no marks visible.

A cedar stump, 34" dia., bears N.38½°W., 68.6 ft., no marks visible.

and the BTs mkd. by Graham in 2005

A fir, 11" dia., bears S.1/4°W., 14.2 ft., with a healed blaze. (Record, S.2°W.)

A fir, 17" dia., bears N.48°W., 19.7 ft., with a healed blaze.

A steel fence post is alongside the cor.

From the corner

E., 225 ft., creek, 3 ft. wide, course N.45°W.