

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 491)

-----  
Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for gr. sec. cor. marked ¼ S on W face; No witness trees. Raised mound of stone alongside on mountain top.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol. 27 Page 11360)

-----  
Point for the ¼ sec. cor. of secs. 29 & 30, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼  
S 30 | S 29  
1950

from which

A hemlock, 10" dia., bears East, 13 lks., mkd: ¼ S29 BT.

A fir, 60" dia., bears S.78°W., 25 lks., mkd: ¼ S30 BT.

The ¼ sec. cor. is located on a spur, which slopes S.55°E.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16746)

-----  
The ¼ sec. cor. of secs. 30 & 29, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the BTs marked in 1950

A hemlock snag, 11" dia., bears East, 13 lks., no marks remaining on burned blaze.

A fir snag, 63" dia., bears S.78°W., 25 lks., with healed blaze.

Set a 5 ft. steel fence post alongside the iron post.

Ron Rice - For: Oxbow Timber 1 LLC - 2/2014 - M167-42

-----  
Found - 2½" GLO brass cap dated 1950 with the following accessories:

Record 11" Hemlock snag East 13 lks. - Missing

63" Fir stump bears S.78°W., 16.5' - HEALED FACE

11 D.Fir bears S.77¼°W., 12.0' - scribing visible (2013 BLM)

2013 BLM tag reads S.77¼°W., 11.3'

9" D.Fir bears S.63°W., 7.5' - scribing visible (2013 BLM) 2013 BLM tag reads S.63°W., 7.8'

continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 18" D.Fir bears S.6°E., 20.3' - blazed, scribed ¼ S29 BT.

11" D.Fir bears N.33°W., 23.7' - blazed, scribed ¼ S30 BT

Steel post adjacent to corner

Note - Corner monument is 0.6' from vertical due to tree root growth. It appears in 2013 BLM tied and referenced the Corner in this position. All references to this corner by Northwest Land Surveying are made to a projected vertical Position.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23188)

-----  
The ¼ sec. cor. of secs. 29 and 30, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs mkd. by Tillman in 1950

A decayed hemlock, size indeterminate, bears East, 8.6 ft., no marks visible.

A fir stump, 74" dia., bears S.78°W., 16.5 ft., with axe marks.

and new bearing trees

A fir, 11" dia., bears S.77¼°E., 11.3 ft., mkd. ¼ S29 BT.

A fir, 9" dia., bears S.63°W., 7.8 ft., mkd. ¼ S30 BT.

Corner is located on the E. side of a fir, 14" dia., on a sharp spur, slopes S.50°E., with a steel fence post alongside the cor.

NAD 1983 (2011)

Latitude: 43°47'56.44" N Longitude: 123°40'47.60" W