

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Pages 491-2)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on N face; from which Hemlock, 5" dia., bears S.10°E., 17 lks., mkd: ¼ S BT. Hemlock, 8" dia., bears N.46°W., 23 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol. 27 Page 11362)

Point for the ¼ sec. cor. of secs. 20 & 29, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼ $\frac{S\ 20}{S\ 29}$
1950

from which
A fir, 60" dia., bears N.20°E., 5 lks., mkd: ¼ S20 BT.
A hemlock, 20" dia. bears S.31°45'W. 58 lks. mkd: ¼ S29 BT

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16747)

The ¼ sec. cor. of secs. 20 & 29, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.

from which the remains of the BTs marks in 1950
A fir snag, 62" dia., bears N.20°E., 5 lks., with healed blaze.
A hemlock snag, 27" dia. bears S.31¼°W. 58 lks., with scribe marks ¼ S29 visible on open & burned blaze. Rescribed ¼ S29 BT on new blaze.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23190-1)

The ¼ sec. cor. of secs. 20 & 29, determined at record bearing & distance from the remains of the BTs mkd. by Tillman in 1950

A decayed fir stump, 70" dia., bears N.20°E., 3.3 ft., with a healed blaze and bearing tree tag.
continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed hemlock, size indeterminate, bears S.31 $\frac{3}{4}$ °W., 38.3 ft., no marks visible.
At the corner point
Reset the Tillman monument; an iron post, found lying loose, 36" long, 1" dia., 29" in the ground, alongside the root of the fir bearing tree stump, with a brass cap mkd. from which new bearing trees
A fir, 17" dia., bears S.45 $\frac{1}{2}$ °W., 11.9 ft., mkd. $\frac{1}{4}$ S29 BT.
A fir, 9" dia., bears N.83 $\frac{3}{4}$ °W., 24.1 ft., mkd. $\frac{1}{4}$ S20 BT.
Corner is located on a spur, slopes S. 35° W., with a steel fence post alongside the cor.

Ronald L Rice - For: Oxbow Timber 1 LLC - Jan. 2015 - M169-8

Found - 1950 GLO brass cap with the following accessories:
62" D.Fir stump bears N.20°E., 3.3' - healed face
Rotted hemlock indeterminate dia. bears S.31 $\frac{3}{4}$ °W., 38.3'
9" D.Fir bears N.83 $\frac{3}{4}$ °W., 24.1' - scribing visible
BLM tagged
17" D.Fir bears S.45 $\frac{1}{2}$ °W., 11.9' - scribing visible
BLM tagged
Aluminum post adjacent to corner.

2