



PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias	Description

BLM dependent resurvey by Edith M Forkner and Aaron M. Graham, Cadastral Surveyors, under Group #2312, surveyed July/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22956)

The ¼ sec. cor. of secs. 32 and 33, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with a brass cap (properly) mkd.

from which the remains of an original bearing tree

A cedar snag, 55" dia., bears S.30°W., 6.6 ft., no marks visible.

and the remains of a bearing tree mkd. by Tillman in 1950

A fir stump, 57" dia., bears N.25°E., 40.3 ft., with a healed blaze.

and the remains of the BTs mkd. by Glenn, et al., in 1967

A decayed hemlock stump, 10" dia., bears S.52°E., 42.9 ft., no marks visible.

A decayed hemlock stump, 22" dia., bears S.80°W., 64.0 ft., no marks visible.

and new bearing trees

A fir, 13" dia., bears N.43½°E., 36.9 ft., mkd. ¼ S33 BT.

A fir, 14" dia., bears N.65½°W., 30.2 ft., mkd. ¼ S32 BT.

Drive an aluminum angle iron, 5 ft. long, alongside the cor., which falls 20 ft. S of a creek, 1 ft. wide, course N.60°W.