

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Rotted fir stump of indeterminate diameter bears N.78°W., 55.4' - no marks
Record 15" Cedar S.15½°W., 42.5 lks. - not found
13" D.Fir bears N.61½°E., 11.5'- scribing visible
BLM tagged
7" D.Fir bears S.34¾°W., 19.2' - scribing visible
BLM tagged
New BTs- 11" D.Fir bears S.52°W., 16.7' - blazed, scribed XBT
10" D.Fir bears N.86°W., 14.7' - blazed, scribed XBT
Steel post adjacent to corner

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23188)

The ¼ sec. cor. of secs. 22 & 27, monumented with an iron post, 1" dia., firmly set, projecting 16" above ground, oriented northwest, with a brass cap (properly) mkd. from which the remains of a bearing tree mkd. by Glenn, et al., in 1967

A decayed fir stump, size indeterminate, bears N.78°W., 55.4 ft., no marks visible.

and new bearing trees

A fir, 14" dia., bears N.61½°E., 11.5 ft., mkd. ¼ S22 BT.

A fir, 7" dia., bears S.34¾°W., 19.2 ft., mkd. ¼ S27 BT.

Drive a steel fence post, found disturbed, alongside the cor.