

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 471)

-----  
Set post, 6" dia., 4 ft. long, in mound of stone, 18" high, 5 ft. sq. base, for cor. to secs. 22, 23, 26, & 27, marked T20S S23 on NE, R8W S26 on SE, S27 on SW, S22 on NW face, with 2 notches on S & E edges. No witness trees.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO records Vol. 27 Page(s) 11342-3)

-----  
Point for the cor. of secs. 22, 23, 26, & 27, determined at the point of intersection of orig. blazed lines, duly identified.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T20S	R8W
<u>S 22</u>	<u>S 23</u>
S 27	S 26
1950	

from which

A fir, 12" dia., bears N.85½°E., 22 lks., mkd: T20S R8W S23 BT.

A fir, 18" dia., bears S.66½°E., 43 lks., mkd: T20S R8W S26 BT.

A fir, 50" dia. bears S.7°W. 43 lks. mkd: T20S R8W S27 BT

A fir, 46" dia., bears N.23½°W., 40 lks., mkd: T20S R8W S22 BT.

The sec. cor. is located on a ridge, the divide bet. Devils Club Creek & South Sister Creek, which bears North & S.5°E.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jolley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16726)

-----  
The cor. of secs. 22, 23, 26, & 27, monumented with an iron post, 2" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the BTs marked in 1950

A burned fir snag, 20" dia., bears N.85½°E., 22 lks., no marks remaining on burned blaze. Rescribed T20S R8W S23 BT on new blaze.

A burned fir snag, 21" dia., bears S.66½°E., 17 lks., no marks remaining on burned blaze.

A burned fir snag, 62" dia., bears S.7°W., 43 lks., no marks remaining on burned blaze. continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A burned fir snag, 46" dia., bears N.23½°W., 40 lks., no marks remaining on burned blaze. Rescribed T20S R8W S22 BT on new blaze.  
 and a new BT  
 A burned fir snag, 39" dia., bears S.31°W., 24½ lks., mkd: T20S R8W S27 BT.  
 Set a post 6 ft. steel fence post alongside the iron post.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2000, surveyed Jan./March 2005 - (DCSO rec. Vol. 55 Page(s) 21757-8)

-----  
 The cor. of secs. 22, 23, 26, and 27, monumented with an iron post, 2" dia., firmly set, projecting 8" above the ground, with brass cap (properly) mkd.  
 from which the remains of BTs mkd. by Tillman in 1950  
 A roothole bears N.85½°E., 14.5 ft., with a down decayed fir lying alongside, size indeterminate, no marks visible.  
 A decayed fir snag, 16" dia., bears S.69½°E., 11.2 ft., with scribe marks 20 8W 26 and other illegible marks visible on partially healed blaze. (Record, S.66½°E.)  
 A burned fir stump, 39" dia., bears S.7°W., 28.4 ft., with scribe mark B visible on partially healed blaze.  
 A fir snag, 48" dia., bears N.23½°W., 26.4 ft., with scribe marks 2 R S B and other illegible marks visible on partially healed blaze.  
 and the remains of a BT mkd. by Glenn, et al., in 1967  
 A fir snag, 39" dia., bears S.31°W., 14.5 ft., with scribe marks T20S R8W S27 BT visible on open blaze. (Record, 16.2 ft.)  
 and new bearing trees  
 A fir, 10" dia., bears N.29½°E., 19.9 ft., mkd. T20S R8W S23 BT.  
 A fir, 10" dia., bears S.80¼°E., 23.7 ft., mkd. T20S R8W S26 BT.  
 A fir, 10" dia., bears S.6°W., 13.4 ft., mkd. T20S R8W S27 BT.  
 A fir, 8" dia., bears N.45°W., 23.0 ft., mkd. T20S R8W S22 BT.  
 Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Ron Rice, NW Land Surveying - March 2013 - C.S. File 65/78-32  
 -----

Condition report  
 Found - 1950 GLO brass cap with the following accessories:  
 continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A roothole bears N.85½°E., 14.5 ft., with a down decayed fir lying alongside, size indeterminate, no marks visible. (Found same)

A decayed fir snag, 16" dia., bears S.69½°E., 11.2 ft., with scribe marks 20 8W 26 and other illegible marks visible on partially healed blaze. (Found same)

A burned fir stump, 39" dia., bears S.7°W., 28.4 ft., with scribe mark B visible on partially healed blaze. (Found same)

A fir snag, 48" dia., bears N.23½°W., 26.4 ft., with scribe marks 2 R S B and other illegible marks visible on partially healed blaze. (Found same)

A fir snag, 39" dia., bears S.31°W., 14.5 ft., with scribe marks T20S R8W S27 BT visible on open blaze. (Found same)

A fir, 10" dia., bears N.29½°E., 19.9 ft., mkd. T20S R8W S23 BT. (Now 12", healed face)

A fir, 10" dia., bears S.80¼°E., 23.7 ft., mkd. T20S R8W S26 BT. (Now 13", healed face)

A fir, 10" dia., bears S.6°W., 13.4 ft., mkd. T20S R8W S27 BT. (Now 13", healed face)

A fir, 8" dia., bears N.45°W., 23.0 ft., mkd. T20S R8W S22 BT (Now 9", healed face)

Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.  
Compass Declination 16° East

Ronald L Rice - For: Oxbow Timber 1 LLC - Aug 2014 - C.S. 65/84-11

Condition report

Found - 1950 GLO brass cap with the following accessories:

- Fd. root hole bears N.85½°E., 14.5'- with a down decayed fir lying alongside, size indeterminate, no marks visible
- 16" decayed fir snag bears S.69½°E., 11.2' with scribe marks 208W 26 and other illegible marks visible on partially healed blaze
- 39" burned fir stump bears S.7°W., 28.4' - with scribe mark B visible on partially healed blaze
- 48" fir snag bears N.23½°W., 26.4' - with scribe marks 2 R S B and other illegible marks visible on partially healed blaze
- 39" fir snag bears S.31°W., 14.5'- with scribe marks T20S R8W S27 BT visible on open blaze
- 12" fir bears N.29½°E., 19.9' - healed face
- 13" fir bears S.80¼°E., 23.7' - healed face Cont.

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>13" fir bears S.6°W., 13.4' - healed face 9" fir bears N.45°W., 23.0' - healed face Steel post adjacent to corner</p>
<p>Fd &amp; used on BLM corrective remonumentation &amp; rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23187-8) Note - Corner is located on the W. edge of a triangular road junction, with an overgrown graveled road, 8 ft. wide, bearing N.20°E., and a steel fence post alongside the cor. From the corner S 65 ft., graveled road, 20 ft. wide, bears N.60°W. and S.25°E., in curve. NAD 1983 (2011) Latitude: 43°48'24.74" N Longitude: 123°37'12.07" W</p>
<p>4</p>