

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; & 34 & 35, T19-8

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 2 Page(s) 462-63)

Set post 6" dia., 4 ft. long, with marked stone, 12" in ground for cor. to secs. 34, 35, 2 and 3, marked T19S S35 on NE.; R8W S2 on SE.; T20S S3 on SW.; S34 on NW. faces, with 4 notches on W. and 2 on E. edges; from which
Fir 30" dia., bears N.77°W., 27 lks. mkd. T19S R8W S34 BT.
Fir 10" dia., bears S.46°W., 12 lks. mkd. T20S R8W S3 BT.
Fir 24" dia., bears S.61°E., 7 lks. mkd. T20S R8W S2 BT.
Hemlock 24" dia. bears N.50°E., 42 lks mkd T19S R8W S35 BT

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 502)

Failed to find the corners on the N. bdy. of T20S R8W, except those on the N. bdy. of sec. 1. After diligent search I fail to find any other of the original marks of this line or any marks of lines coming in from the South. (This excerpt was taken from Vol. 2 Pg. 501)

Set post 4 ft. long, 4" sq., 24" in ground for cor. to secs. 34, 35, 2 & 3, marked T19S S35 on NE.; R8W S2 on SE.; T20S S3 on SW.; S34 on NW. face, with 2 notches on E. and 4 notches on W. edges; from which
A Dogwood 8" dia., bears N.16°E., 123 lks., mkd. T19S R8W S35 BT.
A Fir 18" dia., bears S.15½°E., 17 lks. mkd T20S R8W S2 BT
A Fir 30" dia., bears S.85°W., 31 lks. mkd. T20S R8W S3 BT
A Fir 12" dia., bears N.21°W., 108 lks mkd T19S R8W S34 BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12915)

Point for the sec. cor., as determined from the remains of the original bearing trees:
A Fir stump bears S.15½°E., 17 lks.
A Fir 40" dia., bears S.85°W., 31 lks., showing a healed blaze facing the corner.
A Fir 22" dia., bears N.21°W., 108 lks., showing a healed blaze facing the corner.

At the corner point
Set an iron post, 3 ft. long, 2" dia., 26" in the ground, with brass cap mkd:

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; & 34 & 35, T19-8

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

T19S R8W
 S 34 | S 35
 S 3 | S 2
 T20S
 1952

from which

- A Hemlock 10" dia., bears N.32°E., 122 lks. dist. mkd. T19S R8W S35 BT.
- A Fir 57" dia., bears S.52½°E., 105 lks. dist. mkd. T20S R8W S2 BT.
- A Fir 40" dia., bears N.38°W., 50 lks. dist. mkd. T19S R8W S34 BT.

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16716-17)

 The sec. cor., monumented with an iron post 2" dia., firmly set, projecting 12" above ground with brass cap mkd. in 1952, from which the remaining original bearing tree:

- A Fir 44" dia., bears S.85°W., 31 lks., with healed blaze. and bearing trees mkd. in 1952:
- A Hemlock 18" dia., bears N.37°E., 122 lks. with scribe marks T19S R8W S35 BT visible on open blaze. (Rec. N.32°E.)
- A Fir 60" dia., bears S.52½°E., 105 lks., with no marks remaining on burned blaze. Rescribed T20S R8W S2 BT on new blaze.
- A Fir 38" dia., bears N.38°W., 53 lks., with healed blaze. (Rec. 50 lks.)

Set a 6 ft. steel fence post alongside the iron post.

BLM dependent resurvey by Daniel N. Patterson, Cadastral Surveyor under Group No. 2305, surveyed March/April 2010 (added 12/5/2019 - (DCSO records Vol. 59 Page(s) 23653)

 The cor. of secs. 2, 3, 34, & 35, on the south bdy. of the township, monumented with an iron post, 2" dia., firmly set, projecting 10" above the ground, with brass cap (properly) mkd.

from which the remaining original bearing tree

- A fir, 52" dia., bears S.85°W., 20.5 ft., with a healed blaze.
- and a bearing tree mkd. by Lytle and Norseth in 1952
- A fir, 50" dia., bears N.38°W., 35.0 ft., with a healed blaze.

Continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; & 34 & 35, T19-8

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

and new bearing trees

A fir, 13" dia., bears N.14¼°E., 19.6 ft., mkd. T19S R8W
S35 BT.

A fir, 9" dia., bears N.69½°E., 16.6 ft., mkd. T19S R8W
S35 BT.

There are no suitable trees in sec. 2.

Lat: 43°51'44.67"N Long: 123°37'10.78"W (NAD 1983 (COS 96))

Ronald L. Rice - For: Oxbow Timber 1 LLC - Aug. 2014 - C.S.
file 65/84-10

Found - 1952 GLO Brass cap with the following accessories:
51" D.Fir bears S.85°W. 20.5' - healed face
Record 18" Hemlock bearing N.37°E - Missing
Record 60" Fir bearing S.52½°E - Down
47" D.Fir bears N.38°W., 33.0' - Healed face
8" D.Fir bears N.69½°W., 16.6' - Healed face (2010
BLM tagged)
12" D. Fir bears N.14¼°E 19.6' - Healed face (2010
BLM tagged)
Steel post adjacent to corner

Fd. As per C.S. 65/84-10, 1/2015 - By D. Edwards, M170-32