

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 470)</p> <p>-----</p> <p>Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on N face; from which Alder, 16" dia., bears S.41°W., 95 lks., mkd: ¼ S BT. Alder, 22" dia., bears S.40°E., 105 lks., mkd: ¼ S BT.</p>
<p>BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol. 27 Page 11341)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of secs. 26 & 35, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:</p> <p style="text-align: center;">¼ <u>S 26</u> <u>S 35</u> 1950</p> <p>from which A fir, 20" dia., bears N.17½°E., 50 lks., mkd: ¼ S26 BT. A fir, 40" dia., bears S.83¼°E., 44 lks., mkd: ¼ S35 BT.</p>
<p>Fd. ok, BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16725) - Set a 6 ft. steel fence post alongside the iron post.</p>
<p>Ronald L. Rice, Ward NW Inc. - Jason Collier - Feb. 13, 2012 - C.S. File 65/76-14 & M167-69 (3/2014)</p> <p>-----</p> <p>Found - BLM brass cap, 1950 w/the following accessories: 40" Rotted D.Fir stump bears S.83¼°E., 29.0' - rotted face 20" Rotted D.Fir stump bears N.17½°E., 33.0' - scribing visible</p> <p>New - 15" D.Fir bears N.3°W., 11.0' - blazed, scribed "¼ S26 BT" 19" D.Fir bears S.6°W., 10.9' - blazed, scribed "¼ S35 BT" 16" D.Fir bears S.67°W., 17.6' - blazed, scribed "¼ S35 BT" 17" D.Fir bears N.72°E., 37.7' - blazed, scribed "¼ S26 BT"</p> <p>Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags. Compass Declination 16° East</p>
<p>continued next page</p>

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias	Description

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23185-6)

The ¼ sec. cor. of secs. 26 & 35, perpetuated by Rice, in 2012; monumented with an iron post, 1" dia., firmly set, projecting 1" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs mkd. by Tillman in 1950

A decayed fir stump, size indeterminate, bears N.17½°E., 33.0 ft., with scribe marks S26 BT visible on open blaze.

A decayed fir stump, size indeterminate, bears S.83¼°E., 29.0 ft., no marks visible.

and the bearing trees mkd. by Rice

A fir, 16" dia., bears N.¼°E., 11.0 ft., with scribe marks ¼ S26 BT visible on pitchy open blaze and a nail at the base on the right side center.

A fir, 20" dia., bears S.7¾°W., 11.0 ft., with illegible scribe marks visible on pitchy open blaze and a nail at the base on the right side center.

A fir, 17" dia., bears S.69¾°W., 17.6 ft., with scribe marks ¼ S35 BT visible on pitchy open blaze and a nail at the base on the right side center.

A fir, 17" dia., bears N.71½°W., 37.6 ft., with scribe marks ¼ S26 BT visible on pitchy open blaze and a nail at the base on the right side center.

A steel fence post is alongside the cor.