

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Pages 465-6)

Set post, 4" dia., 4 ft. long, in mound of rock, 18" high, 3 ft. sqr. at base, for qr. sec. cor. marked ¼ S on W face. No witness trees.

BLM dependent resurvey by Thomas A. Tillman, Group # 292, Surveyed June/Oct. 1950 (DCSO records Vol. 27 Page(s) 11337)

Point for the ¼ sec. cor. of secs. 25 & 26, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼
S 26 | S 25
1950

from which

- A fir, 48" dia., bears N.21°45'E., 137 lks., mkd: ¼ S25 BT
- A hemlock, 36" dia. bears N.3°45'W., 29 lks. mkd: ¼ S26 BT

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16719)

The 1/4 sec. cor. of secs. 25 & 26, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd:

from which the remaining BT marked in 1950

- A hemlock, 37" dia., bears N.3¾°W., 29 lks., with healed blaze.

and a new BT

- A burned cedar, 37" dia., bears S.59½°E., 60½ lks., mkd: ¼ S25 BT.

Set a 6 ft. steel fence post alongside the iron post.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23182)

The ¼ sec. cor. of secs. 25 & 26, determined at record bearing and distance from the remains of a bearing tree mkd. by Tillman in 1950

- A decayed hemlock snag, 27" dia., bears N.3¾°W., 19.1 ft., no marks visible.

At the corner point
continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Reset the Tillman monument; an iron post, found disturbed,
36" long, 1" dia., 24" in the ground, with a brass cap mkd.

¼
S 26 | S 25
1950

from which new bearing trees

A fir, 16" dia., bears S.26½°E., 15.7 ft., mkd. ¼ S25 BT.

A fir, 11" dia., bears S.48¾°W., 10.2 ft., mkd. ¼ S26 BT.

Deposit two Mag Nails at the base of the iron post and drive
a steel fence post, found disturbed, alongside the cor.

From the corner

N., 55 ft., creek, 2 ft. wide, course N.65°W.