

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 36

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 465)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for gr. sec. cor. marked 1/4 S on N face; from which
Alder, 16" dia., bears N.42°W., 37 lks., mkd: 1/4 S BT.
Alder, 10" dia., bears S.42°E., 40 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct 1950 (DCSO records Vol 27 Pgs 11336-7)

Point for the 1/4 sec. cor. of secs. 25 & 36, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:
1/4 S 25
S 36
1950

from which
A fir, 60" dia., bears N.65°W., 25 lks., mkd: 1/4 S25 BT.
A cedar, 20" dia., bears S.52°E., 44 lks., mkd: 1/4 S36 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16719)

The 1/4 sec. cor. of secs. 25 & 36, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.
from which the remains of the BTs marked in 1950
A burned fir snag, 60" dia., bears N.65°W., 25 lks., with healed blaze.
A burned cedar snag, 23" dia., bears S.52°E., 44 lks., no marks remaining on burned blaze. Rescribed 1/4 S36 BT on new blaze.
Set a 6 ft. steel fence post alongside the iron post.

David Edwards - For: Oxbow Timber 1 LLC - 1/2015 - M169-1

Found - 1950 BLM brass cap/iron pipe
The snags noted by Jelley in 1967 are now stumps with old BT tags.
New BTs- 12" dia., fir scribed "1/4 S36 BT" bears S.52°E. 11.3'
11" dia., alder scribed "1/4 S25 BT" bears N.40°W., 5.5'
A six ft steel post is set S.84°E., 2 ft.