

PRIMARY CORNER DESCRIPTION SW. Cor. Sec. 31, T20-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 563)

Set post 6" dia., 5 ft. long, 12" in ground with marked stone, mkd. on the NE, T20S S31; R7W S6 on SE.; T21S S1 on SW.; R8W S36 on NW. face, with 6 notches on each edge; raised mound of stone alongside, pits impracticable.

GLO Survey by Thos. Todd, under Contract #574, dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 576)

Closing cor. to Tps. 20 & 21, R7W, which is described as a post 6" dia., with mound of stone; I find the post greatly decayed and the marks nearly obliterated. I destroy all traces of old cor. and re-establish as follows:

Set a post 4 ft. long, 4" sq., 24" in the ground for closing cor. to Tps. 20 & 21 S., R7W., marked CC T20 & 21 S R7W on E.; T21S R7W S6 on S.; T20S R7W S31 on N. face, with 6 notches on each face; from which

A Fir 12" dia., bears N.38°W., 50 lks. dist. mkd. CC T20 & 21 R7W BT.

A Fir 12" dia., bears N.38°E., 55 lks. dist. mkd. T20S R7W S31 BT.

A Maple 10" dia., bears S.40°E., 40 lks. dist. mkd. T21S R7W S6 BT.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #292, Surveyed June/Oct. 1950 (DCSO records Vol. 27 Page(s) 11329)

The cor. of Tps. 20 & 21 S., R7W., on the E. bdy. of T20S R8W, determined at the record bearing and distance from the remaining bearing tree mkd. by Todd in 1891, as follows:

A Fir 26" dia., bears N.38°E., 55 lks. dist. plainly blazed and healed.

At the corner point

Set an iron post, 3 ft. long, 3" dia., 28" in the ground, with brass cap mkd:

		T 20 S
		R 7 W
T 20 S		<u>S 31</u>
R 8 W		S 6
S36		T 21 S
		1950

from which a new bearing tree:

A Fir 10" dia., bears S.89½°E., 60 lks. dist. mkd. T21S R7W S6 BT.

(Cont. Next Page)

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 700116

PRIMARY CORNER DESCRIPTION SW. Cor. Sec. 31, T20-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Remonumentations by Wm. Glenn; C. Albert White; James E. Jelley, Cadastral Surveyors, under Group #'s 350 & 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16698-99)

The cor. of Tps. 20 & 21 S., R7W., monumented with an iron post 3" dia., firmly set, projecting 5" above ground with brass cap mkd. in 1950,

from which the remains of bearing tree mkd. in 1891:

A root hole bears N.38°E., 55 lks. dist., with a down and burned Fir alongside, 27" dia., with healed blaze.

and the remains of the bearing tree mkd. in 1950:

A burned Fir 12" dia., bears S.89½°E., 60 lks. dist. with healed blaze.

and a new bearing tree:

A burned Fir 31" dia., bears N.55°E., 43 lks. dist. mkd. T20S R7W S31 BT.

Set a 5 ft. steel fence post alongside iron post.

Survey by Donald L. Branch - For: International Paper Co. - Nov. 1983 - M 95-66

Found - Std. GLO 2½" I.D. iron pipe, projecting 8" above ground with a ¾" brass cap, properly mkd.

12" Fir, down with blaze, bears East, 60 lks.

27" Fir, down with blaze burnt out, N.38°E., 55 lks.

31" rotten Fir stump, bears N.55°E., 28.45 ft. burnt bad with tree alongside.

New BTs- 8" D.Fir bears N.43°W., 5.5 ft. scribed T20S R8W S BT.

6" D.Fir bears N.39°E., 27.5 ft. scribed T20S R7W S31 BT.

Set 5/8" x 30" Rebar with yellow plastic 1¼" dia. cap mkd. "Branch Eng. L.S. 1137" flush with the ground.

David Edwards - For: Oxbow Timber 1 LLC - 1/2015 - M169-1

Found - 1950 BLM brass cap/iron pipe

A 16" dia. Fir with healed blaze bears N.39°E., 27.5 ft.

A 20" dia fir with healed blaze bears N.43°W, 5.5 ft

Set a 6 ft steel post N.2°E., 2 ft.