



TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Les Roberts, LS 1039 - Sept. 14, 1987 - C.S. 63/50-21  
-----

Corner report

Found - 1953 GLO brass cap bent over from recent logging activity.

60" fir snag, N.43°W., 60.5' (no marks) 1877 BT.

Rec. N.44½°W., 58.1'

20" Maple, S.39°E., 22.1' (Scar vis) 1953 BT rec.

S.36°E., 23.1'

24" Maple, N.53°W., 60.4' (scribe vis.) 1953 BT Rec.

N.53°W., 59.4'

24" Cedar, S.5°W., 34.00' to 6" spike in base  
8/21/1985 RP

40" Maple, N.74°W., 68.60' to 6" spike in base  
8/21/1985 RP

Set - Re-set 1953 GLO brass cap firmly in ground using distance of 34 ft. & 68.6 ft. from 6" spikes set in 8/21/1985. Buried purple magnetic marker under iron pipe.

Set alum. fence post with land survey monument sign attached, beside brass cap. Painted all BTs red

New - Drove 6" spikes into base of 1953 GLO BTs.

20" maple S.39°E., 21.8 ft. to 6" spike.

24" maple N.53°W., 61.2 ft. to 6" spike.

Corner lies about 150 ft. North of Bear Creek & about 30 ft. east of small side creek.