

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Cor. Secs. 20, 21, 28, & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 329-30)

Set a post, 4½ ft. long, 4" sq. 24" in the ground, for cor. to secs. 20, 21, 28, & 29, marked T20S S21 on NE, R9W S28 on SE, S29 on SW, S20 on NW faces, with 2 notches on S & 4 notches on E edges; from which

- A fir, 30" dia., bears N.24°E., 60 lks., mkd: T20S R9W S21 BT.
- A fir, 24" dia., bears S.68°E., 54 lks., mkd: T20S R9W S28 BT.
- A fir, 18" dia., bears S.64°W., 41 lks., mkd: T20S R9W S29 BT.
- A fir, 5" dia., bears N.34½°W., 55 lks., mkd: T20S R9W S20 BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12509-10)

The cor. of secs. 20, 21, 28, & 29, perpetuated with an iron pipe 4 ft. long, 2" dia., fallen over & found lying near the corner point, with iron pipe cap marked

20 21
T 20 S R 9 W
29 28

from which the orig. BTs, which agree with the rec.

- A fir, 52" dia., bears N.24°E., 60 lks., with no marks remaining on badly scale bark blaze. I reblaze this tree below the orig. blaze & mark: T20S R9W S21 BT.
- A rotten fir stump, 36" dia., bears S.68°E., 54 lks., with axe marks in bark found lying at base.
- A fir snag, 18" dia., bears S.64°W., 41 lks., with no marks remaining on burned blaze.
- A double fir stump, 20" dia., bears N.34½°W., 55 lks., sawed off below blaze when larger trunk of tree, 50" dia., was logged. I open pitchy slab lying beside stump & uncover the scribe marks T20S R9W S20 BT.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T20S R9W
S 20 | S 21
S 29 | S 28
1953

from which new BTs

- A fir, 8" dia., bears S.27¼°E., 48 lks., mkd: T20S R9W S28 BT.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 20, 21, 28, & 29

Alias	Description

A fir, 14" dia., bears S.31½°W., 77 lks., mkd: T20S R9W S29 BT.
A fir, 26" dia., bears N.1°45'W., 82 lks., mkd: T20S R9W S20 BT.
Reset the iron pipe, 18" in the ground, alongside the iron post.

Fd. Ok by Les Roberts Dec. 1982 - M90-31
FD. Ok by Les Roberts 10/10/1984 - C.S. File 58/237

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23106-7)

The cor. of secs. 20, 21, 28, and 29, monumented with an iron post, 2" dia., firmly set, projecting 8" above ground with brass cap (properly) mkd.
from which the remains of the original bearing trees
A fir stump, 68" dia., bears N.24°E., 42.1 ft., with a healed blaze. (Record, 39.6 ft.)
A decayed fir stump, size indeterminate, bears S.68°E., 32.2 ft., no marks visible. (Record, 35.6 ft.)
A decayed fir stump, 37" dia, bears N.38°W., 38.6 ft., no marks visible. (Record, N.34½°W., 36.3 ft.)
and the remains of bearing trees mkd. by Tillman and Gawron in 1953-54
A decayed fir stump, 19" dia, bears S.27¼°E., 31.7 ft., with a pitch seam visible on cut top.
A fir stump, 37" dia., bears N.1¾°W., 54.1 ft., with a healed blaze.
and new bearing trees
A fir, 12" dia, bears N.53°E., 25.3 ft., mkd. T20S R9W S21 BT.
A fir, 4" dia, bears S.19½°E., 34.3 ft., mkd. X BT.
A fir, 5" dia, bears S.53°W., 19.7 ft., mkd. X BT.
A fir, 7" dia, bears N.41½°W., 29.9 ft., mkd. T20S R9W S20 BT.
An iron rod, 1/2" dia., firmly set, projecting 18" above ground, established by person(s) unknown, is alongside the cor.
A steel fence post, on top of which is an iron post, 4 ft. long, 2" dia, with brass cap mkd. 20, 21 T20S R9W 29 28, recovered lying loose by Tillman and Gawron in 1953-54, and reset alongside the cor., was found alongside.