

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Wm. Thiel under Contract #260 dated April 17, 1877 - (DCSO records Vol. 1 Page(s) 305)

Set ¼ sec. post between secs. 33 and 4, from which
A Fir 8" dia., bears S.36¼°W., 20 lks. dist.
A Fir 12" dia., bears N.46°E., 20 lks. dist.
A high bald rocky cliff is South about 3 chs.

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 1 Page(s) 366)

The ¼ cor. which is a post, 3 ft. above ground, 3"sq., marked ¼ S on the N. face; from which
A Fir 14" dia., bears N.46°E., 49 lks. dist. mkd. ¼ S BT.
A Fir 12" dia., bears S.36°45'W., 20 lks. dist., marks grown over.

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12450)

The ¼ sec. cor. of secs. 4 & 33, determined at record bearing and distance from each of the original bearing trees, as follows:

A Fir 42" dia., bears N.46°E., 47 lks. dist., plainly blazed and healed. (Gesner rec. 49 lks. dist.)
The shell of a Fir stump 10" dia., bears S.36¼°W., 20 lks. dist., with no marks remaining. (Gesner rec., bears S.36°45'W.)

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

¼ $\frac{S\ 33}{S\ 4}$
1953

from which new bearing trees:

A Fir 15" dia., bears N.18°E., 8 lks. dist. mkd. ¼ S33 BT.
A Fir 10" dia., bears S.54°E., 5 lks. dist. mkd. ¼ S4 BT.

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #'s 350 & 511, surveyed Apr. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14218)

The ¼ sec. cor. of sec. 33 only, T20S R9W., monumented with an iron post 1" dia., extending 10" above ground, with brass cap marked as in 1953,
from which bearing trees mkd. by Tillman in 1953:
(Cont. Next Page)

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 17" dia., bears N.18°E., 8 lks. dist., with healed blaze.

A Fir 12" dia., bears S.54°E., 5 lks. dist., with healed blaze.

In the course of the resurvey of this boundary in 1953, this corner was erroneously remonumented as the ¼ sec. cor. of secs. 4 & 33. I destroy the marks on the SE. bearing tree, remove the marks S4 from the brass cap, and mark a new bearing tree:

A Fir 7" dia., bears N.65°W., 18 lks. dist., mkd. ¼ S33 BT.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1209, surveyed May/Aug 1984 - (DCSO records Vol. 47 Page(s) 18009)

The ¼ sec. cor. of sec. 33 only, on the S. bdy. of the Tp. monumented with an iron post, 1" dia., firmly set, projecting 10" above ground with brass cap mkd. in 1953, from which a bearing tree mkd. by Tillman and Gawron:

A Fir 17" dia., bears N.18°E., 8 lks. dist., with healed blaze.

and a bearing tree mkd. by Peterson:

A Fir 7" dia., bears N.65°W., 15½ lks. dist., with healed blaze. (Rec. 18 lks.)

and a new bearing tree:

A Fir 35" dia., bears N.28°W., 52 lks. dist., mkd. ¼ S33 BT.